

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

**30-005-21162**

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

**LG-2662**

7. Lease Name or Unit Agreement Name:

**Tres Canal State Unit**

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

**Yates Petroleum Corporation**

3. Address of Operator

105 S. 4<sup>th</sup> Street Artesia, NM 88210

7. Well No.

**#1**

8. Pool name or Wildcat

**Wildcat Devonian**

4. Well Location

Unit Letter **K** : **1980** feet from the **South** line and **1980** feet from the **West** line

Section **26** Township **8S** Range **33E** NMPM **Chaves** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

**4347' GR**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE  
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND  
ABANDONMENT ☐

CASING TEST AND  
CEMENT JOB ☐

OTHER: Set casing, cement ☐

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/26/00 - Ran 280 jts (11,643.26') casing set at 11,637' as follows:

37 jts. (1501.13') 5-1/2" 17# P110 SB

243 jts (10,142.13') 5-1/2" 17# P110 Varn


Float shoe set at 11,637'. Float collar set at 11,595'. Bottom marker set at 10,663', top marker set at 9133'.

Cemented with 900 sxs Super C modified with 3% KCL + 8 pps gilsonite + .7% FL-25 + .7% FL-52 (yld 1.61, wt 13.2)

10/27/00 - PD at 2: AM. Bumped plug to 2490 psi for 1 minute. Held OK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE

**Engineering Technician**

DATE **August 28, 2001**

Type or print name

**Susan Herpin**

Telephone No. **505-748-1471**

(This space for State use)

APPROVED BY

TITLE

Orig. Signed by  
**Paul Kautz**  
Geologist

DATE

**5 2001**

Conditions of approval, if any: