

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-21169
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> XX
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Shirkey
8. Well No. 1
9. Pool name or Wildcat West Cato San Andres. Gas

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ XX Other

2. Name of Operator
Primero Operating, Inc.

3. Address of Operator
PO Box 1433, Roswell, NM 88202-1433

4. Well Location

Unit Letter 1 : 1980 feet from the South line and 660 feet from the West line

Section 8

Township 8S

Range 30E

NMPM Chaves

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4038 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. XX PLUG AND ABANDONMENT XXX

CASING TEST AND CEMENT JOB

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

This well was deemed non-commercial due to water, the well was Plugged and Abandoned on January 21, 2002

Plug #1 CIBP at 3050' and dumped 35' of cement on top.

Perforated squeeze holes at 1050' and 600'

Circulated hole with mud and pumped the following plugs:

Plug #2 50 sx, from 1060' to 760'

Plug #2 35 sx from 612, tagged at 480'

Plug #3 10 sx from 30' to surface.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

A dry hole marker will be installed and the location cleaned and leveled to NMOCD standards as soon as possible.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 2/8/02

Type or print name Phelps White

Telephone No. 505-622-1001

(This space for State use)

APPROVED [Signature] BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 10 2003

Conditions of approval if any