

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
S. Caprock Queen Unit

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Chaves County, N.M.

7. UNIT AGREEMENT NAME
S. Caprock Queen Unit

8. FARM OR LEASE NAME
S. Caprock Queen Unit

9. WELL NO.
30-05 - Tr. 6

10. FIELD AND POOL, OR WILDCAT
S. Caprock Queen Unit

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 18

12. COUNTY OR PARISH
Chaves

13. STATE
N. Mexico

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Union Oil of California

3. ADDRESS OF OPERATOR
500 W. Maricofeld - Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
1320 WIL, 130 WIL, Sec. 18, Twn. 15 S, Rng. 31 E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GL 4426

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Procedures Below:

- 1. 8 5/8" @ 303' W/200 Sz.
- 2. 4 1/2" @ 3131' W/300 Sz.
- 3. Puff. @ 3086' - 3099'

Plug #1 - 25 Sz. @ 3100'
Plug #2 - 5 Sz. @ Surface

Recovered 3000' Tubing
Establish Dry Hole Marker

N. D. Oden, Inc.

RECEIVED

APR - 4 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

**Agent for Union Oil
of California**

SIGNED _____

TITLE _____

DATE **March 24, 1972**

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AUG 29 1975
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of putting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED
FEDERAL BUREAU OF INVESTIGATION
U.S. DEPARTMENT OF JUSTICE
APR 11 1964