

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 054900

~~S. Caprock Green Unit~~

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Chaves County, N. M.

7. UNIT AGREEMENT NAME

~~S. Caprock Green Unit~~

8. FARM OR LEASE NAME

~~S. Caprock Green Unit~~

9. WELL NO.

D - Tr. 6 #80

10. FIELD AND POOL, OR WILDCAT

~~S. Caprock Green Unit~~

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18

12. COUNTY OR PARISH

13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Union Oil of California

3. ADDRESS OF OPERATOR
500 N. Marionfeld - Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1325
1326 FNL, 330 FNL, Sec. 18, Twn. 15 S, Rng. 11 E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GL 4426

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Procedures Below:

1. 8 5/8" @ 303' W/200 Sx.
2. 4 1/2" @ 3131' W/300 Sx.
3. Perf. @ 3096' - 3099'

Plug #1 - 20 Sx. @ 3100'
 Plug #2 - 25 Sx. @ 4 1/2" Stub
 Plug #3 - 35 Sx. @ Base of Surface 303'
 Plug #4 - 5 Sx. @ Surface

Establish Dry Hole Marker

H. D. Odell, Inc.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent for Union Oil
of California

DATE

August 11, 1971

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

AUG 18 1971

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
AUG 17 1971
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

847 - 485

RECEIVED

AUG 19 1971

D. C. C.
ARTESIA, OFFICE