

COPIES RECEIVED	
DISTRIBUTION	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-11447	
7. Unit Agreement Name	
North Caprock Queen	
Unit 2	
8. Farm or Lease Name	
Tract #19	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Caprock Queen	
12. County	
Chaves	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator
Anadarko Production Company
3. Address of Operator
PL O. Box 647 Artesia, New Mexico 88210
4. Location of Well
UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 13 S RANGE 31 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
4399 CL

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set abandonment plug at 3020'. Pumped 25' cement on top of plug. Cut off oil string at 945.' Pumped 25 sacks cement at casing cut off point, pumped 25 sacks cement at base of surface casing. Ten sacks at surface with heavy mud between all plugs. Set surface marker and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. N. Muncy, Jr. TITLE Agent DATE 5/10/74

APPROVED BY John W. Ramsey TITLE Center DATE 5/10/74

CONDITIONS OF APPROVAL, IF ANY: