

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OBTAIN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
MURPHY OPERATING CORPORATION
Address of Operator
P. O. Drawer 2648, Roswell, New Mexico 88201
Location of Well
UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 8 TOWNSHIP 13 South RANGE 32 East NMPM.

7. Unit Agreement Name
NORTH CAPROCK QUEEN UNIT #1

8. Farm or Lease Name
North Caprock Queen Unit Tract #27 #1

9. Well No.
5

10. Field and Pool, or Whicat
Caprock Queen (Lea)

12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
4377'

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDON/CHG ☐
WELL OR ALTER CASING ☐	OTHER ☒ shut-in well	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well has been shut-in. The status of this well has changed from producing to shut-in.

PLUG AND ABANDON *effective 6/16/87*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Lois N. Brown
Lois N. Brown
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
TITLE Production Clerk
DATE June 10, 1986
JUN 16 1986

RECEIVED
JUN 11 1986
O.C.D.
HOBBS OFFICE