

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ FEB 21 11 00 AM '67		5. LEASE DESIGNATION AND SERIAL NO. LC-061031
2. NAME OF OPERATOR John N. Trigg		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 106 - Maljamar, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 Feet from North Line & 660 Feet from East Line		8. FARM OR LEASE NAME Trigg Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4282 kb		10. FIELD AND POOL, OR WILDCAT Lasy J
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T13N, R33E
		12. COUNTY OR PARISH Los
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon the above well in the following manner:

1. Set 50 sack cement plug over perforations @ 9500'
2. Fill hole with mud.
3. Cut and pull 5 1/2" casing @ approximately 4000'.
4. Set 50 sack cement plug in and out of casing stuff. (3950' to 4050')
5. Set 20 sack cement plug in top of 9-5/8" casing.
6. Clean up location and erect regulation marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Kenneth E. Apton

TITLE Production Clerk

DATE February 13, 1967

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE _____

FEB 17 1967

*See Instructions on Reverse Side J L GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

687-651

NEW MEXICO OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

(File the original and 4 copies with the appropriate district office)

CERTIFICATE OF COMPLIANCE AND AUTHORIZATION
TO TRANSPORT OIL AND NATURAL GAS

Company or Operator John H. Trigg Lease Federal Trigg lease "A" Federal

Well No. 1 Unit Letter A S 20 T 13S R 33E Pool Lazy "J"

County Lea Kind of Lease (State, Fed. or Patented) Federal

If well produces oil or condensate, give location of tanks: Unit H S 20 T 13S R 33E

Authorized Transporter of Oil or Condensate Texas-New Mexico Pipe Line Company

Address P. O. Box 1510, Midland, Texas

(Give address to which approved copy of this form is to be sent)

Authorized Transporter of Gas _____

Address _____

(Give address to which approved copy of this form is to be sent)

If Gas is not being sold, give reasons and also explain its present disposition:

Reasons for Filing: (Please check proper box) New Well _____ ()

Change in Transporter of (Check One): Oil () Dry Gas () C'head () Condensate ()

Change in Ownership _____ (X) Other _____ ()

Remarks: _____ (Give explanation below)

This well was formerly operated by The Ohio Oil Company

The undersigned certifies that the Rules and Regulations of the Oil Conservation Commission have been complied with.

Executed this the 14th day of April 19 56

Approved _____ 19 _____

OIL CONSERVATION COMMISSION

By C. M. Keady

Title _____

By John H. Trigg

Title Owner

Company John H. Trigg

Address P. O. Box 5629,
Roswell, New Mexico