

1cc- State Land Office

1cc- Mr. FHR-HFD-file


NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	XX	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico

(Place)

July 23, 1958

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

SINCLAIR OIL & GAS COMPANY

(Company or Operator)

STATE 251

Well No. 2 in P

(Unit)

SE 1/4 SE 1/4 of Sec. 21, T. 13S, R. 33E, NMPM, Lazy J (Perm.) Pool

Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

TD 9685- Plug Back 9650' -

Perforations 9510 to 9630'- Present Production 1 Bbl. oil per day-pumping

Reason for plugging- Present Production not profitable- Remedial work this area not profitable.

5 1/2" OD Casing set @ 9685' w/ 500 Sk. - Top cement behind 5 1/2" OD Casing @ 7665'- Propose to set

25 Sk. cement plug f/ Sk 9630' to 9650'- Fill hole w/ heavy mud- Run Magnetor & cut off 5 1/2" OD

Casing @ Approx. 7665'- Set 25 Sk. Cement plug in top 5 1/2" OD Casing Approx. f/ 27630-7696'-

Pull 5 1/2" Casing- Set 25 Sk. cement plug in bottom of 8 5/8" OD Casing set @ 4040' plug f/ 3975 to

4105'- Fill hole w/ heavy mud- Run Magnetor & cut off 8 5/8" OD Casing @ Approx. 1590' (Top cement

behind 8 5/8" OD Casing) Spot 25 Sk. cement plug in top 8 5/8" OD Casing f/ Approx. 1570' to

1612'- Fill hole w/ heavy mud- 13 3/8" OD Casing set 314'- Set 25 Sk. cement plug in f/ 300' to

335'- Fill hole w/ heavy mud to bottom of cellar.

Set 4" "Regulation Marker" extending 4' above surface level in top of 13 3/8" OD Casing and
Bottom of Cellar in 15 Sk. Cement. Fill Cellar & Level Location.Approved....., 19.....
Except as follows:Sinclair Oil & Gas Company
Company or Operator

By.....

Position..... Dist. Supt.
Send Communications regarding well to:Approved
OIL CONSERVATION COMMISSION

By.....

Name..... G. C. Salter, 520 E. Broadway, Hobbs, N.M.

Title.....

Address.....