GNEO OFFIC	Signed by	nplete to the best of my knowledge s		4-7-76
	ation above is true and con			
	May about 1			
5. Install Dry Hole				
5. Install Dry Hole				
5. Install Dry Hole				
5. Install Dry Hole				
E - 1mak-11 Nov. 10-1-	: marker and clea	an location.		
	100 10	D' plug (35 sx.) 1668- D' plug (4 sx.) Surfa	1 <b>56</b> 8'	
	100 100	0' plug (35 sx.) 5212- 0' plug (35 sx.) 4100-	5112 <b>'</b> 4000'	
		)' plug (35 sx.) 6711-		
<ol> <li>Run CIBP and set</li> <li>Run freepoint, c</li> <li>Spot cement plug</li> </ol>	cut 5-1/2" casing	35' cement on plug. g and pull.		
1. Pull pumping equ	uipment.			
7. Describe Proposed or Complet work) SEE RULE 1103.	ted Operations (Clearly sta	ate all pertinent details, and give pe	rtinent dates, inclu	ling estimated date of starting any proposed
OTHER		OTHER		
TEMPORARILY ABANDON PULL OR ALTER CASING	СНА	COMMENCE DRI	<del>  -  </del>	PLUG AND ABANDONMENT
PERFORM REMECIAL WORK	PLU	G AND ABANDON REMEDIAL WOR	·1	ALTERING CASING
Che NOTICE C	eck Appropriate Box OF INTENTION TO:	x To Indicate Nature of Not		Other Data ENT REPORT OF:
		ation (Show whether DF, KT, GR, et		12. County Lea
THE West LINE,		TOWNSHIP 13-S RANGE		MPM.
		OM THE South LINE AND	660 FEET	Lazy J Penn
4. Location of Well				10. Field and Pool, or Wildcat
3. Address of Operator P. O. Box 728 - H	inhhs. New Mexico	88240		New Mexico 'BV' State 9. Well No.
2. Name of Operator TEXACO Inc.				8. Farm or Lease Name NCT-
I. GAS WELL X	OTHER-	FCPM C-1011 FCR SUCA FROPOSALS.]	7	7, Unit Agreement Name
100 NOT USE THIS FORM F	JNDRY NOTICES AN	D REPORTS ON WELLS TO GLIPTIN ON PLOG BACK TO A DIFFERE FORM CHOST FOR DUCK FOR POPOSALS.	ENT AFSERVOIR.	
~.				5, State Oil & Gas Lease No.
OPERATOR .	-			Sa. Indicate Type of Lease State X Fee
U.S.G.S. LAND OFFICE OPERATOR				
LAND OFFICE OPERATOR	NEMY	MEXICO OIL CONSERVATION C	OMMISSION	Supersedes Old C-102 and C-103 Effective 1-1-65

APR? 1976

APR? 1976

OIL CONSERVATION COMM.
NORRS, N. M.