

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10363
7. Unit Agreement Name
8. Farm or Lease Name State 'G'
9. Well No. 1
10. Field and Pool, or Wildcat Saunders
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Tamarack Petroleum Company, Inc.
3. Address of Operator 910 Bank of the Southwest Bldg. Midland, Texas
4. Location of Well UNIT LETTER I , 660 FEET FROM THE East LINE AND 1980' FEET FROM THE South LINE, SECTION 9 TOWNSHIP 14-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4239' K.B.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Production from this well has declined below an economical level and we plan to plug and abandon this well in the following manner-

Plug #1- 25 sx across 5-1/2' csg. Perfs - @ 9936'-9956'.
Plug #2-25 sx across 5-1/2' csg. Stub-
Plug #3-25 sx at 5500' - Glow-Top-
Plug #4-25 sx in and out 8-5/8' shoe - 4183'
Plug #5-25 sx across top of salt -1700'
Plug #6-25 sx in and out of 13-3/8' @ 350'.
Plug #7-10 sx Top of surface.

4' pipe manken to be placed and identified in required manner-

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <i>Robert H. Hulse</i>	TITLE _____	DATE 10/20/67
APPROVED BY <i>Joe O'Haney</i>	TITLE _____	DATE 10/20/67
CONDITIONS OF APPROVAL, IF ANY:		