

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|   |  |  |
|---|--|--|
| <p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</small></p> |  | <p>5a. Indicate Type of Lease<br/>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> |
| <p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>  |  | <p>5. State Oil &amp; Gas Lease No.<br/><b>B-9560</b></p>  |
| <p>2. Name of Operator<br/><b>TEXACO Inc.</b></p>   |  | <p>7. Unit Agreement Name<br/>-</p>  |
| <p>3. Address of Operator<br/><b>P. O. Box 728 - Hobbs, New Mexico 88240</b></p>  |  | <p>8. Form or Lease Name<br/><b>N.M. 'BG' St. NCT-2</b></p>  |
| <p>4. Location of Well<br/>UNIT LETTER <b>A</b> <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>988</b> FEET FROM<br/>THE <b>East</b> LINE, SECTION <b>16</b> TOWNSHIP <b>14-S</b> RANGE <b>33-E</b> N.M.P.M.</p>   |  | <p>9. Well No.<br/><b>1</b></p>  |
| <p>15. Elevation (Show whether DF, RT, GR, etc.)<br/><b>4242' (DF)</b></p>  |  | <p>10. Field and Pool, or Wildcat<br/><b>Saunders - Permo Penn</b></p>                                       |
|   |  | <p>12. County<br/><b>Lea</b></p>   |

|   |   |
|---|---|
| <p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>   |   |
| <p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> | <p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input checked="" type="checkbox"/> <b>Add perforations in Penn Zone</b></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP.
2. Set RBP @ 9960' & packer @ 9790'. Acidize perforations 9826-9944' w/2000 gals. 15% LSTNE acid in 4 equal stages. Use 400# BAF & 800# rock salt between stages. Flush w/50 bbls. produced water.
3. Perforate 4-1/2" casing liner w/2 JSPF @ 9655', 75', 89', 96', 9747', 82', 86', 91', 9814', 21', 67', 9956' & 9968'.
4. Acidize perforations 9655-9968' w/2000 gals. 15% LST-NE acid in 4 equal stages as follows:
  - (1. 500# Benzoic acid flakes & 1000# rock salt followed by 500 gals. acid.
  - (2. 200# Benzoic acid flakes & 400# rock salt followed by 500 gals acid.
  - (3. 200# Benzoic acid flakes & 400# rock salt followed by 500 gals acid.
  - (4. 100# Benzoic acid flakes & 200# rock salt followed by 500 gals acid.
  - (5. Flush w/50 Bbls. produced water.
5. Install pumping equipment. Test and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE Asst. District Supt. DATE 3-31-77

APPROVED BY Jerry Sexton DATE APR 4 1977

CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION COMMISSION

|   |                              |
|---|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.              |                              |
| B-9560                                    |                              |
| 7. Unit Agreement Name                    |                              |
| -   |                              |
| 8. Farm or Lease Name                     |                              |
| N.M. "BQ" St. NCT-2                       |                              |
| 9. Well No.                               |                              |
| 1   |                              |
| 10. Field and Pool, or Wildcat            |                              |
| Saunders-Permo Penn                       |                              |
| 12. County                                |                              |
| Lea                                       |                              |

SUNDY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|   |
|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  |
| 2. Name of Operator   |
| TEXACO Inc.   |
| 3. Address of Operator  |
| P. O. Box 728, Hobbs, New Mexico 88240  |
| 4. Location of Well   |
| UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>988</u> FEET FROM<br>THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14-S</u> RANGE <u>33-E</u> N.M.P.M. |
| 15. Elevation (Show whether DF, RT, GR, etc.)   |
| 4242' (DF)  |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|  |   |  |   |
|--|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>                                       | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>   | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <u>Addl perforations in Penn zone</u> <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install BOP.
2. Acidize 4-1/2" Csg liner perforations 9826'-9944' w/1000 gal. 15% LSTNE Acid. Swab.
3. Perforate 4-1/2" Csg liner w/2 JSPF @ 9747, 82, 86, 91, 9812, 14, 21, & 9822'.
4. If old perforations 9826-9944' unproductive, set CIBP @ 9855' & dump 30' cement on plug. If perforations productive, set RBP @ 9855' & dump 30' sand on plug.
5. Acidize new perforations 9747'-9822' w/2000 gal. 15% LSTNE Acid in 4 equal stages w/200# Rock Salt between each stage. Flush w/75 bbls. water. Swab.
6. Pull RBP. Test & return well to production.

*E. J. ... 11/12/78*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 1-12-77

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

|                 |  |  |
|-----------------|--|--|
| COPIES RECEIVED |  |  |
| DISTRIBUTION    |  |  |
| SANTA FE        |  |  |
| FILE            |  |  |
| U.S.G.S.        |  |  |
| LAND OFFICE     |  |  |
| OPERATOR        |  |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|   |                              |
|---|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.              |                              |
| B-9560                                    |                              |

|  |  |                                |
|--|--|--------------------------------|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small> |  |                                |
| 1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-  |  | 7. Unit Agreement Name         |
| 2. Name of Operator  |  | 8. Farm or Lease Name (NCT-2)  |
| TEXACO Inc.  |  | New Mexico "BG" State          |
| 3. Address of Operator   |  | 9. Well No.                    |
| P. O. Box 728, Hobbs, New Mexico 88240   |  | 7                              |
| 4. Location of Well  |  | 10. Field and Pool, or Wildcat |
| UNIT LETTER <u>A</u> , <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>988</u> FEET FROM   |  | Saunders Permo Penn            |
| THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14-S</u> RANGE <u>33-E</u> N.M.P.M.  |  |                                |
| 15. Elevation (Show whether DF, RT, GR, etc.)  |  | 12. County                     |
| 4242' DF   |  | Lea                            |

|   |  |
|---|--|
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  |  |
| NOTICE OF INTENTION TO:   | SUBSEQUENT REPORT OF:  |
| PERFORM REMEDIAL WORK <input type="checkbox"/><br>TEMPORARILY ABANDON <input checked="" type="checkbox"/><br>PULL OR ALTER CASING <input type="checkbox"/><br>OTHER <u>Extension Request</u> <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/><br>CHANGE PLANS <input type="checkbox"/><br>REMEDIAL WORK <input type="checkbox"/><br>COMMENCE DRILLING OPNS. <input type="checkbox"/><br>CASING TEST AND CEMENT JOBS <input type="checkbox"/><br>OTHER <input type="checkbox"/> |
| ALTERING CASING <input type="checkbox"/><br>PLUG AND ABANDONMENT <input type="checkbox"/>   |  |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## REMARKS

1. WELL STATUS - Abandoned salvage deferred
2. TEMPORARY ABANDONMENT DATE - November, 1969
3. REASON FOR ABANDONMENT - Not profitable to operate.

4. FUTURE PLANS - Plug and Abandon

5. DATE OF FUTURE WORKOVER OR PLUGGING - 1976

*Expires 10-1-76*

|  |                                |                     |
|--|--------------------------------|---------------------|
| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. |                                |                     |
| SIGNED <u>[Signature]</u>  | TITLE <u>Asst. Dist. Supt.</u> | DATE <u>10-7-75</u> |
| APPROVED BY <u>[Signature]</u>   | TITLE <u></u>                  | DATE <u></u>        |
| CONDITIONS OF APPROVAL IF ANY: Insp.   |                                |                     |