V. THO MINACHAES DE	PAHIMEN
Corico accesves	7
PISTRIBUTION	
ANTA FE	
ILE	
J. S. O. S.	
AND OFFICE	
DPERATOR	

Form	C - 1	103	
Revis	ed	10-	1-3

be, er certes		
	——————————————————————————————————————	
DISTRIBL	P. O. BOX 2088	_
ANTAPE	SANTA FE, NEW MEXICO 87501	Form C-103
ILE		Revised 10-
J.8.0.8.		Sa. Indicate Type of Lease
-AND OFFICE		State Y
DPERATOR		1
		5. State Oil & Gas Lease No.
	SUNDRY NOTICES AND DEPORTS OF	890]9
IDO NOT USE	SUNDRY NOTICES AND REPORTS ON WELLS	
	USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
" []	CAB X	7. Unit Agreement Name
ne of Operator	WELL OTHER-	
,-,-,	TEXACO Inc.	8. Farm or Lease Name
<del></del>		New Mexico AN State
dress of Operato		
	P. O. Box 728, Hobbs, New Mexico 88240	9. Well No.
ocation of Well	, 10 NON 10 00240	4
	P 660 South con	18. Field and Pool, or Wildow
UNIT LETTER	TEET FROM THE	Saunders permo peen
East	22	Upper
THE	LINE, SECTION TOWNSHIP RANGENMPI	
	TOWNSHIP RANGE NMP	
MITTELL		
	15. Elevation (Show whether DF, RT, GR, etc.) 4214 (GR)	12. County
mini		Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	Check Appropriate Box To Indicate Nature of Notice, Report or O	
1	NOTICE OF INTENTION TO:	ther Data
	SUBSEQUEN	T REPORT OF:
FORM REMEDIAL WO		
APORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
L OR ALTER CASING	COMMENCE DRILLING OPNS.	L
C ON ACIER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
Rena	ir Waterflow	
STHER	nu cerriow X	
0		
work) SEE RULE	or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including 103.	
	sates, including	estimated date of starting any proposed
٦	DIO UD TUODATA	
⊥.	RIG UP. INSTALL BOP.	
_		
2.	SPOT 30' (5 SX.) SAND ON TOP OF RBP @ 8500'.	
	ON 201 Of RDF 6 0500.	
3.	SET CEMENT RETAINER @ 4775'. CEMENT CASING LEAK	
	6 APPROY ASAGI 407771 CEMENT CASING LEAK	
	@ APPROX. 4846' - 4877' W/ 450 SX. 50-50	POZMIX AND
	CLASS H CEMENT CONTAINING 2% BENTONITE.	11110
•		
4.	SQUEEZE W/ ADDL. 800 SX. CLASS H NEAT CEMENT. RUN	1 MEMPERATURE
	SURVEY TO DETERMINE TOP OF CEMENT. WOC. DOC. TE	TEMPERATURE
	The state of the s	ST.
5.	SET PAKER 0 9650! MDRAM M/ 500	
- •	SET PAKER @ 9650'.TREAT W/ 500 GALS. MUD REMOVELUSH.	'AL ACID AND
	T TIODII •	
	TWO	
	INSTALL PRODUCTION FOUL PMENT THE AND DESCRIPTION TO	
6.	ASOTITIONI TEDI AND SEGUIDE OF	DDODICMICAL
6.	INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN TO	PRODUCTION.
6.	TEST AND RETURN TO	PRODUCTION.
	he information above is true and complete to the best of my knowledge and belief.	PRODUCTION.

ASST DIST MGR PATE August 23, 1983 ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR AUG 24 1983 ITIONS OF APPROVAL, IF ANY

RECEIVED

AUG 23 1983

O.C.D.

তেওঁ হ'ব সংক্রম কর্ম তেওঁ ক্রমেন্ট । ত প্রক্রম সংগ্রিমের তেওঁ তেওঁ ত