DISTRIBUTION SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103
FILE U.S.G.S. LAND OFFICE OPERATOR	THE WILL CONSERVATION COMMISSION	Sa. Indicate Type of Lease State X Fee 5. State Oil & Gas Lease No.
	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT _" IFORM C-101) FOR SUCH PROPOSALS.)	
I. OIL GAS WELL WELL	OTHER-	7, Unit Agreement Name
2. Name of Operator Petroleum Cor	poration of Texas	8, Farm or Lease Name
3. Address of Operator		State "SC"
% Hobbs Pipe & Sup	ply Co., Box 2010, Hobbs, N.M.	1
	660 FEET FROM THE North LINE AND 1980 FEET	10. Field and Pool, or Wildcat Saunders (Permo-Per
	ION 33 TOWNSHIP 14S RANGE 33E N	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16. Charles	Appropriate Box To Indicate Nature of Notice, Report or	Lea
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed O work) SEE RULE 1103.	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS OTHER perations (Clearly state all pertinent details, and give pertinent dates, inclu	ALTERING CASING PLUG AND ABANDONMENT ding estimated date of starting any proposed
2. Propose to spo 3. Propose to spo 4. Propose to spo	et a 25 sack cement plug across perfs a t a 25 sack cement plug at 8000', 5 l, et a 25 sack cement plug at 4141', 8 5, et a 10 sack cement plug at surface wisoaded with mud laden fluid.	/2" casing stub.
2. Propose to spo 3. Propose to spo 4. Propose to spo	ot a 25 sack cement plug at 8000', 5 1, ot a 25 sack cement plug at 4141', 8 5, ot a 10 sack cement plug at surface with	/2" casing stub.
2. Propose to spo 3. Propose to spo 4. Propose to spo	ot a 25 sack cement plug at 8000', 5 1, ot a 25 sack cement plug at 4141', 8 5, ot a 10 sack cement plug at surface with	/2" casing stub.
2. Propose to spo 3. Propose to spo 4. Propose to spo	ot a 25 sack cement plug at 8000', 5 1, ot a 25 sack cement plug at 4141', 8 5, ot a 10 sack cement plug at surface with	/2" casing stub.
2. Propose to spo 3. Propose to spo 4. Propose to spo	ot a 25 sack cement plug at 8000', 5 1, ot a 25 sack cement plug at 4141', 8 5, ot a 10 sack cement plug at surface with	/2" casing stub.
2. Propose to spo 3. Propose to spo 4. Propose to spo	ot a 25 sack cement plug at 8000', 5 1, ot a 25 sack cement plug at 4141', 8 5, ot a 10 sack cement plug at surface with	/2" casing stub.
2. Propose to spo 3. Propose to spo 4. Propose to spo 5. Hole will be 1	ot a 25 sack cement plug at 8000', 5 1, ot a 25 sack cement plug at 4141', 8 5, ot a 10 sack cement plug at surface with	/2" casing stub.