1962 APR	4	AM	10 :	30	(Form C-102 (Revised 7/1/52
TOOP IN IT			1() R	-0	(Revised 7/1/02

NUMBER OF COPIE	S RECEIVE	5	
DIS	TRIBUTION		
SAFTA FE			
FILE			
U. S. G. S.			
LAND OFFICE			
TRANSPORTER	OIL		
IRANSPORTER	GAS		
PRORATION OFFI	CE		
00504700			

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be

	Indicate Nature of Notice by	Checking Be	yow		
OTIGE OF INTENTION CHANGE PLANS	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper		
otice of Intention Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner		
otige of Intention Squeeze	Notice of Intention to Acidize	Х	Notice of Intention to Shoot (Nitro)		
otice of Intention Gun Perforate	Notice of Intention TO (Other) DRILL OUT CIB	X	Notice of Intention (Other)		
IL CONSERVATION COMMISS	ION Roswell, N	w Mexico	April 9	. 19 6 2	
ANTA FE, NEW MEXICO	(Place)		(Date)		
.1					
entlemen:					
_	n to do certain work as described below				
Shell 011 (Company Sta Observed 14S 39E9 34 T, T	UC A 	Well Noin	(Unit)	
NW SE Was Sec	34 14s 39E	NAMPA	Saunders	Ро	
Lea.					
1. Treat perforations	ollow instructions in the R 9770' - 9810' w/1500 gall n bridge plug.@ 9832'.				
 Drill out cast iron Re-open perforation Pump test and place 	ns 9842' - 9856'.				
3. Re-open perforation	ns 9842' - 9856'.				