

MAR 2 1970

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ALTA FE	
FILE	
U.S.G.S.	
AND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name State "A"
9. Well No. 8
10. Field and Pool, or Wildcat Saunders (Permo-Penn)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER-
1. Name of Operator Petroleum Corporation of Texas		
2. Address of Operator % Hobbs Pipe & Supply Co., Box 2010, Hobbs, N.M.		
3. Location of Well UNIT LETTER B , 990 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 34 TOWNSHIP 14S RANGE 33E NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.) 4208' DF
--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Propose to spot a 25 sack cement plug at 10,057'.
- Propose to spot a 25 sack cement plug at 8000', 5 1/2" casing stub.
- Propose to spot a 25 sack cement plug at 4211', 8 5/8" casing shoe.
- Propose to spot a 25 sack cement plug at 600', 8 5/8" casing stub.
- Propose to spot a 25 sack cement plug at 356', 13 3/8" casing shoe.
- Propose to spot a 10 sack cement plug at surface with marker.
- Hole will be loaded with mud laden fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Agent</u>	DATE <u>12-8-69</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		