

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/> <b>XX</b>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator <b>Petroleum Corporation of Texas</b>		8. Farm or Lease Name <b>Shell Gray</b>
3. Address of Operator <b>c/o Hobbs Pipe &amp; Supply Co. P.O. Box 2010 Hobbs, N M</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>N</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>35</b> TOWNSHIP <b>14S</b> RANGE <b>33E</b> NMPM.		10. Field and Pool, or Wildcat <b>Saunders (Permo-Penn)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4191' D.F.</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 35 sx. cement plug across perforations at 9966'-9896'.
2. Spotted a 25 sx. cement plug at 5½" casing stub at 1900'.
3. Spotted a 25 sx. cement plug at 8 5/8" casing shoe at 1650'.
4. Spotted a 10 sx. cement plug at surface with marker.
5. Hole was loaded with mud laden fluids..

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Agent DATE April 13, 1970

APPROVED BY *[Signature]* TITLE Geologist DATE MAY 5 1971

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

**APR 16 1970**

**OIL CONSERVATION COMM.  
HOBBS, N. M.**