

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISIO
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- RE-Entry	7. Unit Agreement Name Duncan Unit
2. Name of Operator Harvey E. Yates Company	8. Farm or Lease Name
3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE W LINE, SECTION 26 TOWNSHIP 13S RANGE 35E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4041' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/12/81 - 1/14/81

Ran various flat bottom mills and dress-off mills to clean out inside and dress off top of 9 5/8" csg stub at 1159' without success.

1/15/81 POH, LD Mill & DC's. Went in hole open ended and set following cement plugs:

1. 100' plug (68 sxs) @ 1159'
2. 100' plug (67 sxs) 50' in & 50' out of 13 3/8" csg @ 361'
3. 30' plug (15 sxs) @ surface
4. Welded on Dry Hole Marker

P&A @ 5:00 p.m. 1/15/81

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Harder TITLE Engineer DATE 1/21/81

APPROVED BY David Cutanach TITLE OIL & GAS INSPECTOR DATE NOV 16 1983

CONDITIONS OF APPROVAL, IF ANY: