

Orig: &amp; co: 908

cc: MRQ

JTR

F

## NEW MEXICO OIL CONSERVATION COMMISSION

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

March 25, 1952

Date

Hobbs, New Mexico

Place

Following is a report on the work done and the results obtained under the heading noted above at the

Sinclair Oil & Gas Co. John Shults Well No. 3 in the  
Company or Operator Lease  
NE/4 SE/4 of Sec. 13, T. 12S, R. 37E, N. M. P. M.,  
Gladiola Pool Lee County.

The dates of this work were as follows: March 21, 1952

Notice of intention to do the work was (was not) submitted on Form C-102 on March 21, 1952,  
and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Set 4442' of 8 5/8" @ 4444' from surface with 1500 sacks of cement - circulated to surface.

Let set 48 hours and tested W/1200# pump pressure - Tested OK and resumed drilling.

Witnessed by V. D. Tatum Arrow Drlg. Co. Driller  
Name Company Title

APPROVED:  
OIL CONSERVATION COMMISSION

W. G. [Signature]  
Name  
Title

I hereby swear or affirm that the information given above is true and correct.

Name W. G. [Signature]  
Position  
Representing  
Company or Operator  
Address

Date

19

