

C  
O  
P  
Y

May 13, 1959

Mr. R. P. Brewer  
Monterey Oil Company  
Post Office Box 2157  
Midland, Texas

Re: Plugging and Abandoning of  
Solman No. 1 Well - Unit 0  
Sec. 22-T128-R37E

Dear Mr. Brewer:

In relation to our telephone conversation on May 12, we have checked other wells in the Gladiola area and feel that the San Andres has possibilities of being productive.

On the subject well, we desire a plug below the zone of porosity at 5300 feet of 25 sacks of cement, and 25 sacks at 5100 feet. The following plugs are to be placed above this zone of porosity:

25 sacks in and out of 8-5/8  
25 sacks at 8-5/8 stub  
25 sacks at top of salt  
25 sacks at base of 13-3/8  
25 sacks at top of 13-3/8

If you have any questions regarding this matter, please contact us.

Very truly yours,

OIL CONSERVATION COMMISSION

Eric F. Engbrecht  
District Engineer

efe/ug  
cc: Mr. A. L. Porter, Jr.  
Mr. R. P. Montgomery

