

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator MOSS PETROLEUM COMPANY (214) 754-2984	5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
3. Address of Operator 2121 SAN JACINTO STREET #970 DALLAS, TX 75201	6. State Oil & Gas Lease No. 008090
4. Well Location Unit Letter <u>C</u> : <u>1980</u> feet from the <u>WEST</u> line and <u>660</u> feet from the <u>NORTH</u> line Section <u>26</u> Township <u>12S</u> Range <u>37E</u> NMPM County <u>LEA</u>	7. Lease Name or Unit Agreement Name: D. P. PECK
8. Well No. 1	
9. Pool name or Wildcat GLADIOLA-WOLFCAMP	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3898 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SET CIBP @ 9651 WITH 35' PLUG ON TOP. MAY HAVE STUCK PACKER DOWNHOLE AND WILL ADVISE IF REQUIRED. SHOOT 5 1/2" CASING 6000' IN AN ATTEMPT TO PULL CASING AND WILL SET 100' PLUG IN AND OUT OF STUB. SET 100' PLUG @ 4888' ACROSS 8 5/8 WITH 50' BOTH IN AND OUT. SET 100' PLUG FROM 286' TO 386' ACROSS 13 3/8" CASING SHOE. SET 10 SXS SURFACE PLUG AND MARK.

TAG TAG  
TOP OF SALT  
F/2375 to 2275

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE 1/19/00

Type or print name DANIEL P. LITTLE

Telephone No. (214) 754-2984

(This space for State use)

APPROVED BY [Signature] TITLE ORIGINAL FILED BY DATE 08 2000

Conditions of approval, if any: