NO. OF COPIES RECEIVED			Form Coy03
DISTRIBUTION			Supersedes Gd C-102 and C-103
ANTAFE	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-650
ILE			47
.s.g.s.			Sa. Indicate Type of Lease
AND OFFICE			State Fee 🛣
PERATOR			5. State Oil & Gas Lease No.
	 !		
SLIN	IDDY NOTICES AND REPORTS ON	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
	TEXTION FOR PENNIT OF A SAME OF A SA		7. Unit Agreement Name
OIL GAS WELL WELL	OTHER Temporarily Aband	ioned in Penn. Zone	
Name of Operator			8. Farm or Lease Name
Ton I Incre	•		Midhurst
Tom L. Ingram Address of Operator			9. Well No.
9 0 Boy 17	57 - Roswell, New Mexico		2
Location of Well	or - nosuerry new reactor		10. Field and Pool, or Wildcat
•	1880 FEET FROM THE North	1880	Southwest Gladiola Pen
UNIT LETTER	FEET FROM THE	LINE AND FEET F	TITITION TO THE TOTAL MARKET
line t	ection 35 township 12-5	s 37-E	
THE West LINE, S	TOWNSHIP TOWNSHIP	RANGE	:PM. (
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	3894' KB		Lee
	ck Appropriate Box To Indicate N		
			Г
TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	CASING TEST AND CEMENT JOB	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING		COMMENCE CRILLING OPNS.	PLUG AND ABANDONMENT
OTHER 7. Describe Proposed or Complete work) SEE RULE 1103.	change plans	commence critting opns. casing test and cement Job other Temporary Ab tails, and give pertinent dates, inclu	endonment ding estimated date of starting any propos
other 7. Describe Proposed or Complete work) SEE RULE 1103.	CHANGE PLANS	commence critting opns. casing test and cement Job other Temporary Ab tails, and give pertinent dates, inclu	PLUG AND ABANDONMENT

CONDITIONS OF APPROVAL, IF ANY: