

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. **C. G. Staley**, Roswell, N. Mex., 19____
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon drilling Well
No. 1 in SE $\frac{1}{4}$ of Sec. SE $\frac{1}{4}$ of Sec. 29, T. 13 S., R. 37 E.,
N. M. P. M., wild cat Oil Field, Lea County.
We plan to commence work on _____, 19____.

The reasons for wishing to abandon the well are as follows:

The Well has been drilled to 5230 with neither oil nor gas encountered.

The present condition of the well is as follows:

Casing was set at top of the salt shutting off all water and no water was encountered below the salt, the Well was dry when drilling was stopped at 5230.

The work which we propose to do in abandoning the well is as follows:

Fill with mud from bottom of hole to about 2310, then run ten sacks of cement filling hole to top of the salt and directly below the eight inch casing set at 2270, fill with mud completely to the top of the hole.

Approved Jan 4, 1929

Except as follows:

Sincerely yours,

C. E. Reynolds

Company or Operator.

By J. W. Brown

Position Field Manager

Send communications regarding this well to

Name _____

Address _____

C. G. Staley
State Geologist or Oil and Gas Inspector.

574