

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO. 30-025-05090
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name GECKO Lowe et. al.
2. Name of Operator GECKO, Inc.	8. Well No. 1
3. Address of Operator 310 W. Wall, Suite 702- LB106, Midland, TX 79701	9. Pool name or Wildcat Wildcat
4. Well Location Unit Letter <u>C</u> : <u>815</u> Feet From The <u>North</u> Line and <u>2307</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>13S</u> Range <u>37E</u> NMMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) N/A	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIH with tubing. Spot 259 sx Class -C- cement at 586'. SDFN.
2. RIH. Tagged plug at 248'. PLUG #1 586--248' (259 sx).
3. Spot 20 sx. Class -C- cement from 20' to surface. PLUG #2 20' to surface (20 sx).
4. Cut off wellhead. Install dry hole marker. Back fill pits. Clean location.

Well P&A 08/23/95

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve L. Thomson TITLE President DATE 09-05-95  
TYPE OR PRINT NAME Steve L. Thomson TELEPHONE NO. (915) 686-0121

(This space for State Use)  
APPROVED BY Jack Griffin TITLE OIL CONSERVATION DIVISION DATE 09-05-95  
CONDITIONS OF APPROVAL, IF ANY: