

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DO, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-05093

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator
Paladin Energy Corp.

8. Well No.
3

3. Address of Operator
10290 Monroe Drive, Suite 301, Dallas, TX 75229

9. Pool name or Wildcat
King SWD

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 35 Township 13S Range 37E NMMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-14-02 Rig up unit, POOH w/ production pipe.
11-15-02 RIH w/ tbg., set down @ 4553', spot 85 sx cmt. @ 4553' (okayed by Billy Prichard, O.C.D.). Sqz. plug (WOC for 4 hrs.) tag plug @ 4533', re-spot 30 sx @ 4533' (suggested by Billy Prichard w/ O.C.D.) WOC.
11-18-02 Tag cmt. plug @ 4378', mud up hole, test csg. @ 600 PSI (okay). Spot 30 sx cmt. @ 2000', spot 30 sx @ 410' WOC.
11-19-02 Tag cmt. plug @ 315', spot 10 sx cmt. to surface (60-0').
Cut off wellhead, install dry hole marker, clean location.

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 11-20-02
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 915-530-0907

(This space for State Use)

APPROVED BY _____ DATE _____
ORIGINAL SIGNED BY _____
COUNTY REPRESENTATIVE II/STAFF MANAGER