

Continued:

Abandoned this zone by placing cast iron bridge plug at 8,500' and dumping 2 sxs.
of cement on top of it.

Well is Temporarily Abandoned until it can be decided whether to permanently
abandon it or use it as a disposal well.

1. I HAVE BEEN ADVISED
A. THAT THE WELL IS TO BE
S TO THE WELL AND YOUR
FUTURE PLANS FOR THE WELL