

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

DEC 29 10 42 AM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Sinclair Oil & Gas Company	5. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>Last</u> LINE, SECTION <u>5</u> TOWNSHIP <u>12S</u> RANGE <u>38E</u> NMPM.	8. Farm or Lease Name Kendrick Estate
	9. Well No. 1
	10. Field and Pool, or Wildcat Gladiola Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3866' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1193.

12-4-65 Pulled 2-7/8"OD tubing. Ran 7" Baker Cast Iron Bridge Plug and set @ 9410'. Displaced 2 sacks cement on top of Bridge Plug, top of cement @ 9398'. Filled hole w/heavy mud.

12-11-65 Shot off 7"OD casing @ 4996' and pulled.

12-19-65 Displaced 25 sacks cement in top of 7"OD casing stub @ 4996'. Displaced 25 sacks cement plug in bottom of 9-5/8"OD casing @ 4533'. Displaced 10 sacks cement in top of 9-5/8" casing and collar, set regulation dry hole marker, cleaned and levelled location. Plug and Abandon eff: 12-19-65

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: [Signature] TITLE: Superintendent DATE: 12-27-65

APPROVED BY: [Signature] TITLE: _____ DATE: _____

CONDITIONS OF APPROVAL, IF ANY:
Orig&2cc: OGC Hobbs, cc: regional Office, cc: file