

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 21 11 40 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug and Abandon	7. Unit Agreement Name
2. Name of Operator Sinclair Oil & Gas Company	8. Farm or Lease Name Clovis K. Hendrick
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>12S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Gladola Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3872' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-4-65 Set 5-1/2" Cast Iron Bridge Plug @ 11,950' and dumped 2 sacks cement, top of plug to 11,931'. Filled hole w/heavy mud.
12-30-65
12-31-65 Shot off 5-1/2"OD casing @ 4820' and pulled. Mixed 25 sacks cement and set plug @ 4820'. Mixed 25 sacks cement and set plug bottom of 9-5/8"OD casing @ 4499'. Mixed 10 sacks cement and capped 9-5/8"OD casing and cellar, installed registration dry hole marker, cleaned and levelled location. Plug and Abandon effective 1-6-66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 1-10-66

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

Orig&2cc CCC Hobbs; cc: Regional Office; cc: file