

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-71

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Carr Well Service, Inc.	8. Farm or Lease Name Z. Taylor
3. Address of Operator P.O. Box 69090, Odessa, Texas 79769-9090	9. Well No. 2
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 12S RANGE 38E N.M.P.M.	10. Field and Pool, or Wildcat Gladiola - Miss.
15. Elevation (Show whether DF, RT, GR, etc.) 3,784 GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CIBP @ 9300' W/35' cement
100' Plug @ 5870'
100' Plug @ 4650' Tag
100' Plug @ 2275'
10 Sx @ Surface
100' Plug 50' in and 50' out of cut.

*Food hole w/ mud 10 lb brine w/ 25 lb gel
barri*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce M. [Signature] TITLE Cementer DATE 12/30/88

APPROVED BY [Signature] TITLE Geologist DATE JAN 12 1989

CONDITIONS OF APPROVAL, IF ANY: