

Orig: & cc: OCC
cc: VDA
JTR
F

(Form C-103)
(Revised 7/1/52)

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON Deepened (Other) Plug back & Perforate	

March 27, 1953

(Date)

Hobbs, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Sinclair Oil & Gas Company

(Company or Operator)

Rosa Shults

(Lease)

Warren-Bradshaw Exploration Co.

(Contractor)

Well No. 1 in the SW 1/4 SW 1/4 of Sec. 18

T. 12 S, R. 38 E, NMPM., Wildeat Pool, Lea County.

The Dates of this work were as follows:

Notice of intention to do the work (was) (was not) submitted on Form C-102 on _____, 19____, and approval of the proposed plan (was) (was not) obtained. (Cross out incorrect words)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Deepened from 12025 to 12217 W/ DST every 15 feet - No Oil recovery

3-11-53 Set Halliburton DM retainer @ 11890 and squeezed with 250 sacks of cement, squeezing off perforations in 5 1/2" casing 11963 to 12020.

3-12-53 Perforated 5 1/2" casing from 9628 to 9650 with 88 - 1/2" jet shots. Ran 9666' of 2" tubing with packer set @ 9588. Swabbed 22 hours, recovered 2 Bbl. of oil, 37 Bbl. of load water and 140 Bbl. of Salty Sulphur water.

3-15-53 Set Halliburton DM retainer @ 9600 and squeezed off perforations 9628 to 9650 with 50 sacks of cement.

3-19-53 Set Halliburton DM retainer and resqueezed with 50 sacks of cement.

3-24-53 Drilled cement to 9642. Perforated 5 1/2" casing from 9630 to 9640 with 40-1/2" jet shots. Swabbed 9 hours, all water. No show of oil or gas.

Witnessed by: Harold W. Shaner, Sinclair Oil & Gas Co., Foreman
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: _____

Position: Dist. Supt.

Representing: Sinclair Oil & Gas Co.

Address: Box 197 Hobbs, N.M.

(Title)

(Date)