STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

WE. OF COPIES SCEELVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.5.		
LAND OFFICE		
OPERATOR	1	

OIL CONSERVATION DIVISION

Form C-103 -

1ANTA FE	SANTA FE, NEW	MEXICO 87501			Revised 10-1-7
FILE			150	ı. Indicate Typ	e of Lease
U.S.G.#.				State	Fee X
LAND OFFICE					
OPENATOR			5.	, State OII & G	ias Lease No.
				Fee	
SUNDRY (DO NOT USE THIS FORM FOR PROPILESTION	NOTICES AND REPORTS ON OSALS TO DAILL OR TO DEEPEN OR PLUG AN FOR PERMIT -" (FORM C-101) FOR SUC	WELLS ACK TO A DIFFERENT RESER H PROPUBALS.)	VOIR.		
,				. Unit Agreeme	at Name
OIL X WELL	OTHER-			None	
Name of Operator			8.	. Farm or Leas	e Name
Tri-State Prod	oduction & Supply Inc.			M. Powell	
, Address of Operator			9.	. Well No.	
Box 1182	Hobbs. Ne	ew Mexico 88	240	1	
Location of Well				0. Field and P	ool, or Wildcat
P 99 0	FEET FROM THE East	330	G:	ladolia	Devonian
UNIT LETTER	FEET FROM THE	LINE AND	FEET FROM	mm	
South	18 TOWNSHIP 12Sout	th 38 Red	>+		
THE LINE, SECTION	TOWNSHIP TOWNSHIP	NANGE JO BO	NMPM.		
mmmm	15. Elevation (Show whether I	DE RT CR ata)		2. County	777777
		or, Kr, OK, etc.)	1.		
	3865.5 G.L.			Lea	_7////////
Check A	ppropriate Box To Indicate N	ature of Notice, Re	port or Other	Data	
NOTICE OF INT		·	BSEQUENT R		:
•					
	r				RING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	1 1	ALTE	
7	PLUG AND ABANDON		. H		, ,
EMPORARILY ABANDON		COMMENCE DRILLING OPN	}		AND ABANDONMENT
HODINAR Y LI RAROGIA	PLUG AND ABANDON	COMMENCE DRILLING OPH	apr.	PLUG	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORALILY ABANGON PULL OR ALTER CASING		COMMENCE DRILLING OPN	apr.	PLUG	AND ABANDONMENT

Change of operator name from Tri-State Production & Supply to Tri-State Production & Supply Inc.

eby certify that the information above is true and complete to the bast of my knowledge and belief. Aubrey E. Kenyan				
TITLE President	DATE 12-27-81			
	DATE			