Submit 3 Copies to Appropriate District Office State of New Mexico
Energy, Mais and Natural Resources Department

Form C-103 Revised 1-1-89

District Office				
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-07210	
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE FEE X		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL WELL WELL	OTHER	oil	L & M	
2. Name of Operator		<u> </u>	8. Well No.	
F1k Oil Compa	nv		11	
3. Address of Operator	•		9. Pool name or Wildcat	
P.O. Box 310	Roswell N.M.		Gladiola Wolfcamp	
4. Well Location Unit Letter::	467 Feet From TheNorth_	Line and	467 Feet From The West. Line	
Section 20	Township 12S Ran	nge 38E	NMPM Lea County	
	10. Elevation (Show whether	DF, KKB, KI, GK, EIC.)	<i>\(\(\(\(\(\(\(\)\\\\\\\\\\\\\\\\\\\\\\</i>	
	Appropriate Box to Indicate N	Vature of Notice R	Penort or Other Data	
	Appropriate Box to indicate Interest in the control of the control	SUE	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT	
	5121132 12113	CASING TEST AND C		
PULL OR ALTER CASING	L-1	OTHER:		
OTHER:				
12. Describe Proposed or Completed Operark) SEE RULE 1103.	crations (Clearly state all pertinent details, ar	nd give pertinent dates, incl	uding estimated date of starting any proposed	
11-14-1991 Set CIBP @ 9450' and dump 35' cement on top				
11-18-1991 Pull 4530' of 5 1/2" casing				
11_18_1881 Spot 25 sxs @ 5050-4950'				
11-18-1991 Spot 90 sxs @ 4586'-4362' tagged				
11_10_1091 Spot 50 sxs @ 2050-1950'				
11-20-1991 Spot 100 sxs @ 1050' - 890' tagged				
11-20-1991 Spot 100 sxs @ 400'-283' tagged				
11-20-1991 Spot 10 sxs @ 20' to surface				
		- Ia		
Ir Ho	nstall dry hole marke ble circulated with	er 10# mud		
	CATION CLEAN & READY FOR			
I hereby certify that the jufformation above is	true and complete to the best of my knowledge and		- /- /aa	
SIONATURE		mue <u>President</u>	DATE 5/7/93	
Joseph J. (kelly		TELEPHONE NO.	
TYPE OR PRINT NAME				
(This space for State Use)	, ,	OH: C C	10 INTODOMINO MAY 17 1000	
APTROVED BY Jack	Briffin T	me OIL & GA	AS INSPECTOR MAY 1 7 1993	
CONDITIONS OF APPROVAL, IF ANY:	<i>,</i> •			

C gn