

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-476

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amini Oil Corporation	8. Farm or Lease Name State E-476 "A"
3. Address of Operator 400 Wall Towers West - Midland, Texas	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>380</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>12-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Gladiola (Wolfcamp)
15. Elevation (Show whether DF, RT, GR, etc.) 3886' D.F.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

1. Set 30 sk. Plug @ 9550' and fill hole with mud laden - Fluid 9.5 lbs. or better.
2. Top of cement behind 5-1/2" casing @ 2925'
3. Pull 5-1/2" casing from 2920'
- * 4. Set 10 sk. Plug in top of 9-5/8" casing
5. 9-5/8" casing. Set @ 4506'. 1600 sk. circulated.
6. Set marker and clean up location.

* 25 sk IN & out Steel 5 1/2" csg. - See to Mr. M.D. FRAIZER 11-18-69

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joselyn Broom TITLE Agent DATE Nov. 17, 1969

APPROVED BY Leshie A. Clements TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: