

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Barnes & Golden	
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 1	
4. Location of Well UNIT LETTER <u>N</u> , <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>13S</u> RANGE <u>38E</u> N.M.P.M.		10. Field and Pool, or Wildcat Bronco Wolfcamp	
15. Elevation (Show whether DF, RT, GR, etc.) 3800' GR		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	Mississippi zone only <input type="checkbox"/>
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned the Mississippian zone in the following manner:

1. Rigged up on 7/26/76, installed BOP & POH w/completion assy.
2. RIH w/5½" cmt retr on tbq & set retr @ 10,883'.
3. Pumped thru retr w/100 sx Cl H cont'g .6% Halad 22 & 5# salt/sk & 50 sx Cl H cont'g .4% HR-4 followed by 50 sx Cl H cont'g .4% HR-4 & 5# sd/sk into perfs 10,983-11,014'. MP 1000#. FP vacuum. WOC. Squeezed perfs 10,983-11,014' w/150 sx Cl H cmt cont'g .4% HR-4. Max & final press 3000#. Rev out 25 sx. Mississippian zone abandoned eff 7/29/76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry S. Smith

TITLE Dist. Drlg. Supv.

DATE 8/18/76

APPROVED BY Dist. 1, Supv.

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: