

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name Barnes & Golden
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201	9. Well No. 2
4. Location of Well UNIT LETTER K, 1650 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 13-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Bronco-Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3800' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned in the following manner:

Set CIBP in 7" casing @ 11050' and capped w/4 sx of cement w/dump bailer. Shot off 7" casing @ 4891', recovered 161 jts of 7" casing= 4891'. Used 9#/gallon gel mud to spot the following cement plugs: 40 sx Class "A" neat cement from 4811-4956'; 40 sx Class "A" neat cement from 4593-4693' (in and out of 9-5/8" shoe). Shot off 9-5/8" casing @ 604', recovered 19 jts 9-5/8" 36# casing. Spotted 40 sx Class "A" neat cement from 574-634' (across 9-5/8" stub); 40 sx Class "A" neat cement 303-343', and set 10 sk Class "A" cement plug in top of 13-3/8" casing. Installed dry hole marker. 13-3/8" casing remains intact. Job complete 5/27/70.

Your office will be advised when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A.D. Litcher</u>	TITLE <u>Dist. Drlg. Supervisor</u>	DATE <u>6/3/70</u>
APPROVED BY <u>John W. Ramsey</u>	TITLE <u>Geologist</u>	DATE <u>JUN 20 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 2 1970

OIL CONSERVATION COM. 1
HARRIS