

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No. V-961	
7. Unit Agreement Name	
8. Farm or Lease Name Le Bough 5 State	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
11. Elevation (Show whether DF, RT, GR, etc.) 4295' (GL)	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER: Re-Entry	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator Box 1933, Roswell, NM 88201	
4. Location of Well UNIT LETTER K 1980 FEET FROM THE South 1980 THE West LINE, SECTION 5 TOWNSHIP 13-S RANGE 33-E	

10. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPWS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	
OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 1) POH w/tbg. GIH & set 5½" CIBP @ 9450' (40' above perfs @ 9490') & dump 35' cmt on top. POH.
- 2) GIH & pump 100' plug from 8850' to 8750' (top of Wolfcamp). POH.
- 3) GIH & free point 17# K-55 5½" csg (TOC @ 8602' by CBL, free pipe indicated @ 8540'). Cut csg @ 8500' & pull.
- 4) GIH & pump 100' plug (50' in & 50' out of 5½" csg stub) & tag.
- 5) Pump 100' plug from 7550' to 7450' (Abo).
- 6) Pump 100' plug from 6790' to 6690' (Glorieta).
- 7) Pump 100' plug (50' in & 50' out of 8-5/8" csg shoe) @ 3940'.
- 8) Pump 100' plug from 1640' to 1540'.
- 9) Pump 50' surface plug & install dry hole marker.

Verbal per Eddie Cee & Jerry Sexton.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Eddie W. Seay</u>	TITLE <u>Prod Mgr/Res. Engr</u>	DATE <u>8-26-85</u>
APPROVED BY <u>Oil & Gas Inspector</u>	TITLE _____	DATE <u>AUG 30 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

AUG 28 1986

LIBRARY
HOBBS 21910