

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No.
2. Name of Operator Cherry Butcher Cabot Corporation		7. Unit Agreement Name
3. Address of Operator c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N. M.		8. Farm or Lease Name Austin State
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>14-S</u> RANGE <u>36-E</u> NMPM.		9. Well No. <u>1</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4002' D.F.</u>		10. Field and Pool, or Wildcat <u>Wildcat</u>
12. County <u>Lea</u>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

1. Propose to spot a 15 sx cement plug from 10,357'-10,367'.
2. Propose to spot a 25 sx cement plug at 2-7/8 casing stub at 6000".
3. Propose to spot a 25 sx cement plug at 8-5/8 casing shoe at 4640'.
4. Propose to spot a 25 sx cement plug at 8-5/8 casing stub at 1000'.
5. Propose to spot a 25 sx cement plug at 13-3/8 casing shoe at 418'.
6. Propose to spot a 10 sx cement plug at surface with marker.
7. Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 1/7/72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE JAN 26 1972
 CONDITIONS OF APPROVAL, IF ANY: