

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20689
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Pride Energy Company		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 701602, Tulsa, OK 74170		7. Lease Name or Unit Agreement Name:
4. Well Location Unit Letter M : 660 feet from the South line and 660 feet from the West line Section 1 Township 12 S Range 34 E NMPM County Lea		8. Well No. 1-1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,152 GR		9. Pool name or Wildcat <del>Wildcat</del> Four Lakes Miss

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Completion <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Washed down wellbore, ran lead seal casing patch on 9 5/8", 47 ppf, N-80, LT&C casing, slipped patch over casing stump and set seals with 60,000#s tension. Ran 5 1/2" casing down to 12, 324'. Ran 2 7/8" tubing, N-80, 7.9# down to 12,153' with Arrow set packer set at 12,024' with 10,000# psi tension. Perforated Mississippi formation 12,105-108; 12,110-116; 12,121-152 with 5 spf. Tested on 7/26/01 at 536 MCFPD, 0 BOPD, 10 BWPD, 18/64 chk., FTP 680, LP 680. Tested on 8/9/01 at 460 MCFPD, 3 BOPD, 0 BWPD, FTP 680, LP 680.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>John W. Pride</u>	TITLE <u>President of Pride Oil &amp; Gas Co., Inc. as General Partner of Pride Energy Company</u>	DATE <u>9/6/01</u>
Type or print name <u>John W. Pride</u>	Telephone No. <u>918-524-9200</u>	

(This space for State use)

APPROVED BY _____	TITLE <u>PETROLEUM ENGINEER</u>	DATE _____
-------------------	---------------------------------	------------

Conditions of approval, if any:

Jp2535.hq

ALL-IED  
Hobbs  
CCO