

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION


Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No.
1. Name of Operator TEXACO Inc. 2. Address of Operator P.O. Box 728 - Hobbs, New Mexico 88240 3. Location of Well UNIT LETTER 0 650 FEET FROM THE South LINE AND 1800 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 12-S RANGE 38-E N.M.P.M.		7. Unit Agreement Name 8. Farm or Lease Name H.H. Harris 9. Well No. 2 10. Field and Pool, or Wildcat Bronco Siluro Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3900' (DF)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☒ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐		SUBSEQUENT REPORT OF:
---	--	------------------------------

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods, pump and tubing. Clean out.
2. Perforate 2-7/8" OD csg w/2 JSPF @ 11,827', 29' & 11,831'.
3. Set pkr @ 11,708'. Acidize perforations 11,827-11,831' w/6000 gals. 20% NE-GR acid.
4. Install pumping equipment. Test and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED 	TITLE Asst. District Supt.	DATE 8-24-78
APPROVED BY Barry Stetson	TITLE Dist. 1. Supt.	DATE AUG 25 1978
CONDITIONS OF APPROVAL, IF ANY		