

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
E-2109	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name STATE "CY"
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER M 660' FEET FROM THE South LINE AND 612' FEET FROM THE WEST LINE, SECTION 30 TOWNSHIP 12-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat HIGHTOWER, E. LOWER PENN
15. Elevation (Show whether DF, RT, GR, etc.) 4229' RD B	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well no longer economical to produce. Workover on re-completion prospects doubtful - Propose to P/A as follows:

Load Hole w/ mud -
Spot 25 5x cement plug 10,300' - 10,150' (Plugs 10,223' - 10,252')

Shoot + pull 5 1/2" Csg:
If below 6000' - 35 5x in + out of Stub, 35 5x 5600' - 5400'.

" 5500' - 35 5x 3500' - 3400'.

" above 5500' - 35 5x in + out of Stub.

Spot 25 5x in + out of 8 5/8" CSA 4091'.

Shoot + Pull 8 5/8" - Spot plugs - 25 5x in + out of Stub if below 500' & 25 5x - 13 7/8" shoe @ 410'.

If above 500' - only " " " " "

10 5x @ surface & erect P/A marker - Make final cleanup.
13 7/8" CSA 410' Circ 5 1/2" CSA 10374' w/ 525 5x.
8 5/8" CSA 4091' w/ 800 5x.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE AREA SUPERINTENDENT

DATE

MAR 15 1971

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Geologist

DATE

MAR 17 1971