

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No. <b>E-1027</b>
2. Name of Operator <b>TEXACO Inc.</b>		7. Unit Agreement Name
3. Address of Operator <b>P. O. Box 728, Hobbs, New Mexico 88240</b>		8. Farm or Lease Name <b>New Mexico 'CZ' State</b>
4. Location of Well UNIT LETTER <b>B</b> <b>710</b> FEET FROM THE <b>North</b> LINE AND <b>2030</b> FEET FROM THE <b>East</b> LINE, SECTION <b>14</b> TOWNSHIP <b>12-S</b> RANGE <b>34-E</b> NMPM.		9. Well No. <b>3</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4167 (DF)</b>		10. Field and Pool, or Wildcat <b>Ranger Lake Penn</b>
12. County <b>Lea</b>		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well has been plugged and abandoned as listed below:

1. Loaded hole with mud. Could not unseat packer. Unable to get through at 4200'.
2. Cut off tubing at 4150' and pulled. Cut off 4-1/2" OD casing at 4120' and pulled.
3. Spotted 50 sx cement plug 4070 to 4170'.
4. Spotted 10 sx cement plug at surface.
5. Set 4" marker extending 4' above ground level and clean location. Plug and abandon complete February 20, 1970.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Assistant District Superintendent** DATE **February 26, 1970**

APPROVED BY *[Signature]* TITLE **Geologist**  
 CONDITIONS OF APPROVAL, IF ANY:

RECEIVED 1970  
APR 21 1970