NEW MEXICO OIL CONSERVATION COMMISSION Substitute Su	NO. OF COPIES RECEIVED		Form C-103
NEW MEXICO OIL CONSERVATION COMMISSION Control Conservation	DISTRIBUTION		
Solidate Type of Lease Sump Solidate Type of Lease Sump Solidate Type of Lease Sump Solidate Sump	SANTA FE	NEW MEXICO OIL CONSERVATION C	
SUNDRY NOTICES AND REPORTS ON WELLS TOD 187 AND "ALL SECURITY OF THE PARTY OF THE	FILE		HUG / Francisco Transfer
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS OF NOTICE OF INTERPRETATION OF THE PROPERTY OF THE P			t vsd. intricate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS Columbia Colum			
2. Name of Operator TEXAS PACIFIC OIL COMPANY Post Office Box 1069 - Hobbs, New Mexico 88240 2. Location of Well Loc	OPERATOR		
TEXAS PACIFIC OIL COMPANY TEXAS PACIFIC OIL COMPANY 3. Form of lease Name TEXAS PACIFIC OIL COMPANY 5. Address of Operation Post Office Box 1069 - Hobbs, New Mexico 88240 2. Location of Well 1. Location of Well	SUNDR (DO NOT USE THIS FORM FOR PUSE "APPLICAT	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFE (ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	RENT RESERVOIR.
State "F" 3. Solitons of Operator Post Office Box 1069 - Hobbs, New Mexico 88240 4. Location of Wolf 1. 2050 1. Feet Frage Tag South 1. South 1. Soliton whether DF, RT, GR, etc.; 4217 GR Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: THE AND ABANDON THE CARD ABA	OIL GAS WELL	OTHER- P & A	
Post Office Box 1069 - Hobbs, New Mexico 88240 2. Location of Well Unit Letter L 2050 First from the South Inc AND 1990 First from the South Inc AND I		PANY Inc	1
South South Letter L 2050 FEET FROM THE SOUTH LARY 990 FEET FROM THE LARY J Penn THE West IDM, SECTION 35 TOWNSHIP 13-S RAISE 33-E MANNIEL SOUTH LARY J Penn 15. Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: PERFORM MEMEDIAL WORK TEMPORALLY ARABON CANNIEL PRINCE CASING FLUG AND ARABON CONTROL OF SECTION STREET FROM THE CONTROL OF STREET FRO			
L 2050 SEET THOU THE SOUTH 13-S AND 33-E MORE AND JOURNAL TO SEET THE WEST INFORMATION TO: THE WEST INFO. SECTION 35 TOWNSTIF 13-S AND 33-E MORE AND INFO. SECTION TO SECTION TO SEE TOWNSTIF 13-S AND SECTION TO SEE TOWNSTIF INFO TO SEE TOWNSTIF INFO TO SECTION TO SEE TOWNSTIF INFO TO SECTION SECTION TO SECTION SECTIO		Hobbs, New Mexico 88240	
West LIMI, SECTION 35 TOWNSHIP 13-S ANGE 33-E ANGE 33-E LIGHT AND			
15. Elevation (Show whether DF, RT, GR, etc.) 4217 GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM MEMEDIAL WORK TEMPORABLY ABANDON PULL OR ALTER EASING OTHER 17. Describe Proposed or Completed Operations (Clearly store all pertinent details, and give pertinent dates, including estimated date of starting any proposed by SEE PULL 1103. Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. @ 8525'. 2. Pulled tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: TITLE Area Production Foreman PLIC General PLIC County Lease 11. Area Production Foreman PLIC Ann Apart School PLIC County Lease 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: TITLE Area Production Foreman PLIC School PLIC County Lease 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. PLIC School PLIC County Lease 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: TITLE Area Production Foreman PLIC School PLIC County Lease Altering Cashway Alt	UNIT LETTER L 20	South Line and	990 Lazy J Penn
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABLY ABANDON PULL ON ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propounts) see Fulle 1:10. Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2' csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2'' csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby certify that the information ubove is true and complete to the best of my knowledge and belief. Original signed by: THE Area Production Foreman Date 8-11-69		10 0	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM MEMERIAL WORK TEMPORATION ADDRESS THE PROPOSE OF INTENTION TO: PULC AND ABANDON TEMPORATION ADDRESS THE PROPOSE OF INTENTION TO: PULC AND ABANDON THE CASING TEST AND CEMENT JOB OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Longieted Toporations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Longieted 25 sacks cement over perfs @ 9725-85'. 2. Pulled thgs. & short off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby centify that the information above is true and complete to the best of my knowledge and belief. O'. R. Tilley YILLE AREA Production Foreman DATE 8-11-69	THE West LINE, SECTS	on TOWNSHIP RANGE	33-E NMPM.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM MEMERIAL WORK TEMPORATION ADDRESS THE PROPOSE OF INTENTION TO: PULC AND ABANDON TEMPORATION ADDRESS THE PROPOSE OF INTENTION TO: PULC AND ABANDON THE CASING TEST AND CEMENT JOB OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Longieted Toporations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Longieted 25 sacks cement over perfs @ 9725-85'. 2. Pulled thgs. & short off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby centify that the information above is true and complete to the best of my knowledge and belief. O'. R. Tilley YILLE AREA Production Foreman DATE 8-11-69	mmmm	15 Flooring (Show what or DE DT CD	12 County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: DERFORM REMEDIAL WORK TEMPORABLE ADARDON PULL ON ALTER CASING OTHER OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prope work) see Notice 1103. Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg, & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg, & shot off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg, & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 300'; 25 sks. at 300'		11111	
NOTICE OF INTENTION TO: PEEF CRAM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDON PLUG AND ADANDON PLUG AND ADANDON PLUG AND ADANDON PLUG AND ADANDON PLUG AND ADANDONMENT CASHE TEST AND CEMENT JCD PLUG AND ADANDONMENT JCD PLUG AND ADADDONMENT JCD PLUG AND ADANDONMENT JCD PLUG AND ADADDONMENT JCD PLU			
TEMPORABLEY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed by proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed by proposed by proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed by proposed b	NOTICE OF I	ITENTION TO:	SUBSEQUENT REPORT OF:
OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed for Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed for Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed for Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed for Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed for Complete Total Date (Complete Starting any proposed for Complete Operations) 1. Rean tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2' csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2'' csg. 4. Ran tbg. & spotted 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: Original signed by: TITLE Area Production Foreman DATE 8-11-69	Ħ		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed by SEE ROLLE 1103. Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: C. R. Tilley THILE Area Production Foreman DATE 8-11-69			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Hobbs Pipe and Supply Company plugged well as follows: 1. Ran thg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled thg. & shot off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran thg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: C. R. Tilley THEE Area Production Foreman DATE 8-11-69	PULL OR ALTER CASING		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed (No. 103). Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: Original signed by: Original signed by: Title Area Production Foreman DATE 8-11-69	OTHER	OTHER	
Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2" csg. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: C. R. Tilley THEE Rea Production Foreman DATE 8-11-69	OTHER		
Hobbs Pipe and Supply Company plugged well as follows: 1. Ran tbg. & spotted 25 sacks cement over perfs @ 9725-85'. 2. Pulled tbg. & shot off 4-1/2" cag. @ 8525'. Not gree - shot @ 8000'. 3. Recovered & layed down 241 jts. 4-1/2" csg. 4. Ran tbg. & spotted 25 sks. cement at 7703'; 25 sks. cement at 6910'; 25 sks. at 4148'; 25 sks. at 800'; 25 sks. at 362'; 10 sks. at surface. 5. Removed wellhead and installed dry hole marker. Filled cellar and cleaned location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Original signed by: C. R. Tilley TILLE Area Production Foreman DATE 8-11-69		perations (Clearly state all pertinent details, and give p	pertinent dates, including estimated date of starting any proposed
Original signed by: SIGNED C. R. Tilley TITLE Area Production Foreman DATE 8-11-69 APPROVED BY DATE	1. Ran tbg. & spotted 2. Pulled tbg. & shot 3. Recovered & layed 4. Ran tbg. & spotted 25 sks. at 800'; 2	25 sacks cement over perfs @ 972 off 4-1/2" csg. @ 8525'. Not gradown 241 jts. 4-1/2" csg. 25 sks. cement at 7703'; 25 sks. 5 sks. at 362'; 10 sks. at surface	cee - shot @ 8000'. cement at 6910'; 25 sks. at 4148';
APPROVED BY John W. Renyan TITLE Feologist DATE	Original signed by	7.	
	SIGNED C. K. Tilley	TITLE ATEX FIODUC	DATE 0-11-07
	APPROVED BY W.		DATE