DISTRIBUTION		
		Form C-103 Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION.	C-102 and C-103
FILE	HEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	# 3 [] 1 8 명	5a. Indicate Type of Lease
LAND OFFICE	та 11 . д. 1Н 167 г.	State Fee.
OPERATOR		5. State Oil & Gas Lease No.
OPERATOR		J. State off & das Lease No.
CUIDD	(NOTICES AND DEPONDED AND WELL AND	minimum de la composición dela composición de la composición de la composición de la composición de la composición dela composición de la composición de la composición de la composición dela composición de la composición de la composición dela composición de la composición de la composición de la composición dela composición de la composición dela composición dela compo
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1.	IN FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL WELL	OTHER.	
2. Name of Operator		8. Farm or Lease Name
eh-11	w 641 Campan	William Sanders
3. Address of Operator	y 011 Company	9, Well No.
2.0	No. 790 Wohle Wass Marries	•
4. Location of Well	Box 730, Hobbs, New Mexico	10. Field and Pool, or Wildcat
_	ARA Would AAA	T FROM LASY 11 JH Penn
UNIT LETTER	660 FEET FROM THE NOTTH LINE AND 660 FEE	T FROM
 .		
THE LINE, SECTION	TOWNSHIP 148 RANGE 338	NMPM. ()
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
$\frac{1}{1}$	Unknown	Los (IIIIIIII
Check A	ppropriate Box To Indicate Nature of Notice, Report of	or Other Data
NOTICE OF INT	TENTION TO: SUBSEQ	UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER	OTHER	
17. Describe Froposed or Completed Ope work) SEE RULE 1103.	erations (Clearly state all pertinent details, and give pertinent dates, inc	
17. Describe Proposed or Completed Ope work) SEE RULE 1103. Spudded well on A BJ R-3 Casing at Plug down 6:30 Actested casing to		11-3/4"00 31.200 Armco SW y pump and plug process. e surface. WOC 24 hours

CONDITIONS OF APPROVAL, IF ANY: