Submit 3 Copies to Appropiate District Office	State of New Mex Energy Minerals and Natural Res	ources Department		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION P.O. Box 2088		WELL API NO. 30-025-22111	
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 8	7504-2088	5. Indicate Type of Lease	ATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease N	0.
(DO NOT USE THIS FORM FOR P DIFFERENT RES (FORM	TICES AND REPORTS ON WELL ROPOSALS TO DRILL OR TO DEEPEN O ERVOIR. USE "APPLICATION FOR PER C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agr	eement Name
i. Type of Well: OL. WELL XX WELL) onex		Childress A	NKV
2. Name of Operator			8. Well No.	
YATES PETROLEUM CORP	ORATION		2	
3. Address of Operator	Artocia NM 88210		9. Pool name or Wildcat Saunders Permo	Lazy J Upper Penn
4 Well Location	eet - Artesia, NM 88210			
Unit Letter \underline{L} : $\underline{1}$	980 Feet From The South	Line and 66	0 Feet From The	West Line
			NMPM Lea	County
Section 1	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)		
	4196' DF	Jature of Notice R	eport or Other Data	
	k Appropriate Box to Indicate I		SEQUENT REPO	
NOTICE OF I	NTENTION TO:	301	_	
		REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRILLIN		
]	CASING TEST AND C		
OTHER:		OTHER: Re-entr		X
<pre>work) SEE RULE 1103. 8-16-94 - TOOH with d bit left in 5-1/2" ca 7-5/8" slip joint and 6 joints of 5-1/2" 17 Picked up on pipe. L over stub. Nippled d and BOP. TIH w/4-3/4 Swallow 1-1/2'. TOOH not feel top of stub. clean. TOOH. 8-17-94 - TOOH with 4 Log CCL across casing thru perforations 2.5 stinger and tubing. Pacesetter Lite, 4/10</pre>	1	4-3/4" drill co Installed 5-1/2 ". TIH w/141 j 6609'. Rigged essure to 1000# off and dress 5 " drill collars ars. TIH with 4 0-6740' - string lumberger. TIH les at 6630'. L /2" SV EZ drill bed 40 bbls mud. acesetter Lite.	llars. Pilot col 2" rams and BOP. Dints of 5-1/2" 1 up pump. Pressur . Good indicatio -1/2". Nippled u . Set down on fi -3/4" bit and col ers. TIH to 6942 w/4" casing gun J oaded hole with J retainer at 6570" Mixed and pumpe Tailed in with J CONT	lar and 4-3/4" Made up 5.5# and red to 800#. on slip joint up tubinghead sh at 6609'. lars. Did 2'. Circulated 4' (4 shots) - 17 bbls. Pumped 4. TIH with red 300 sacks 100 sacks
(This space for State Use)			an an an Argina. An Argina	ACO DE TECH
		πιε	1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 -	
ATTRONED BY		111LE		

Definition Definition DEFINICIAL OIL CONSERVATION DIVISION P.O. Box 2088 DETINICIAL DEFINICIAL DETINIC	o Appropriate District Giffice	Energy Minerals and Natural Resources Departm	Form C-103 nent Revised 1-1-89
BO, Bos 1990, Hobs, NM, 88240 P.O. Box 2088 30-025-22111 Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 30-025-22111 PCD Box 2008, Roll Rev Mexico 87504-2088 Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 DISTRICT III Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 SUNDARY NOTICES AND REPORTS ON WELLS Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 SUNDARY NOTICES AND REPORTS ON WELLS Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 Sundary State FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 SUNDARY NOTICES AND REPORTS ON WELLS Smart FC, New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 Sundary State State FC, New Mexico 87504-2088 New Mexico 87504-2088 Smart FC, New Mexico 87504-2088 Sundary State Sta		-	
FO. Draver DD. Areaia, NM \$2310 STATE FEE STETICLTIIL G. Sare COLA, Astee, NM \$7410 STATE FEE SUNDRY NOTICES AND REPORTS ON WELLS G. Sare COLA, Astee, NM \$7410 State Colarse NM (DO NOT USE THAS FORM FOR PROPOSALS TO BUIL OF TO DEFEN OR PENMIT F. Lease Name or Unit Agreement Name (DO NOT USE THAS FORM FOR SUCH PROPOSALS) The POPM COLON FOR REMAINT The Competence of the Colon FOR SUCH PROPOSALS) 1. Type of WG: WGL ONER Childress AKV YATES PETROLENT RESERVER, USE 'APPLICATION FOR REMAINT The Velocity of the Competence of the Colon FOR SUCH PROPOSALS) 1. Type of WG: ONER E. Well No. YATES PETROLENT CORRECTION State of Operator 1. Type of WG: ONER State of Operator 1. Type of WG: ONER State of Operator 1. State of Operator State of Operator State of Operator 1. State of Operator Interview of The State of Notice, Report, or Other Data Lee Sector Toronship 145 Rese 335 MATM County 4. UPG ARILY BANDON Childress ARY ALTERNO CASING County County County ALTERNO CASING County	DISTRICT I P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088	1
1000 Ris Brack RA, Ales, M. 19410 2 1000 Ris Brack RA, Ales, M. 19410 2 1000 RIS DERISTING SALL OR TO DEFLOR TO DEFLOR OR PLUG BACK TO A DEFERENT RESERVORE USE "APPLICATION FOR PERMIT" (FORM 6-101) FOR SUCH PROPOSALS) 1. Type of Well: 2 Name of Ogenator YATES PERIOLEUM CORPORATION 2 Name of Ogenator YATES PERIOLEUM CORPORATION 3. Address of Ogenator YATES PERIOLEUM CORPORATION 4. Well Loadion 105 South Fourth Street - Artesia, NM 88210 3. Saunders-Permor Byper Pénn 4. Well Coalidor 10. Toweshie 11. Toweshie 12. Deck Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: 12. Deckin Propositor Class of PLUG AND ABANDON 13. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: 14. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:	<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088	The Trans of Long
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEPEND OF PLOUD BUCK TO A presented Name of Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS) 7. Lase Name of Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Weit (FORM C-101) FOR SUCH PROPOSALS) 8. Weil No. 2. Name of Openator 8. Weil No. 2. Name of Openator 8. Weil No. 2. Name of Openator 9. Pool name or Widat (CORPORATION) 3. Addees of Openator 9. Pool name or Widat (CORPORATION) 4. Weil Location 105 South Fourth Street - Artesia, NM 88210 105 South Fourth Street - Artesia, NM 88210 Saunders-Permo Hypers Telon 4. Weil Location 104 Sector 105 South Fourth Street - Artesia, NM 88210 Saunders-Permo Hypers Telon 4. Weil Location 105 South Fourth Street - Artesia, NM 88210 Line and 660 Feel From The Kest Line 9. Dool name of Widat (Core of NTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS Comment of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING </td <td>DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410</td> <td></td> <td>6. State Oil & Gas Lease No.</td>	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEPEND OF PLOUD BUCK TO A presented Name of Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS) 7. Lase Name of Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Weit (FORM C-101) FOR SUCH PROPOSALS) 8. Weil No. 2. Name of Openator 8. Weil No. 2. Name of Openator 8. Weil No. 2. Name of Openator 9. Pool name or Widat (CORPORATION) 3. Addees of Openator 9. Pool name or Widat (CORPORATION) 4. Weil Location 105 South Fourth Street - Artesia, NM 88210 105 South Fourth Street - Artesia, NM 88210 Saunders-Permo Hypers Telon 4. Weil Location 104 Sector 105 South Fourth Street - Artesia, NM 88210 Saunders-Permo Hypers Telon 4. Weil Location 105 South Fourth Street - Artesia, NM 88210 Line and 660 Feel From The Kest Line 9. Dool name of Widat (Core of NTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS Comment of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING </td <td></td> <td>TIGES AND REPORTS ON WELLS</td> <td></td>		TIGES AND REPORTS ON WELLS	
Citiz ES Contract Childress AKV 2 Name of Opensor 8. Well No. 2 Arres of Opensor 9. Pool same of Wildsat (2000) 3. Address of Opensor 9. Pool same of Wildsat (2000) 9. Pool same of Wildsat (2000) 4. Weil Localion 9. Pool same of Wildsat (2000) 9. Pool same of Wildsat (2000) 2. Market of Opensor 1 Township 145 2. Weil Localion 1 Township 145 Range 33E NMPM Lea Section 1 Township 145 Range 33E NMPM Lea Commit 9. Pool same of Wildsat (2000) 10 Elevacian (Show whather DP, REB, RT, GR, acc) 10. Commit 10. 9. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING 1011. DOLL OR ALTER CASING Commit (Check PLANS) Comment of Substantion and and and and period and and and opensions (Check Plans) 112. Describe Proposed or Completed Opensions (Check state all period attate, including estimated date of staring any proposed work) SEE RULE 1003. Continued period opensions (Check state all period attate, in	(DO NOT USE THIS FORM FOR PI	ROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK ERVOIR. USE "APPLICATION FOR PERMIT"	TO A 7. Lease Name or Unit Agreement Name
WELL ONC I. Well Na. YATES PETROLEUM CORPORATION I. Well Na. 3. Address Opendor Saunders-Permo Hyper Pann 4. Well Location In Later L. : 1980 Feet From The South Lise and 660 Feet From The West Lise 4. Well Location In Later L. : 1980 Feet From The South Lise and 660 Feet From The West Lise 105 South Fourth Street - Artesis, NM 88210 Saunders-Permo Hyper Pann Kest Lise 4. Well Location In Later L. : 1980 Feet From The South Lise and 660 Feet From The West Lise 106 Elevision (Show whith DF, RKB, RT, GR, etc.) 4196' DF Internot SUBSEQUENT REPORT OF: 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PEFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: Re-entry & completion E 112 Describe Proposed or Completed Operations (Chearly rate all perimers details, and give perimers dates, including estimated date of staring any proposed word SEE RULE 103. OTHER: Re-entry & completion E 12 Describe Proposed or Completed Operations (Chearly rate all perinensi dates, including estimated date of staring any proposed word	- 210		Childress AKV
YATES PETROLEUM CORPORATION 9. Pool name of Wilder Lagy J 3. Address of Operator 9. Pool name of Wilder Lagy J 105 South Fourth Street - Artesia, NM 88210 9. Pool name of Wilder Lagy J 4. Well Laction 1. 1980 Feet From The South Line and 660 Feet From The West Line Section 1 Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4. 196' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Altrening CASING PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND CEMENT JOB OTHER OTHER OTHER Research of Completed Operations (Chardy state all periment data), and give periment data, including enimated date of staring any proposed verit SE RULE 103. COLLardy state all periment data). Sting out of retainer. TOOH. Show TINUED FROM PREVIOUS PAGE: Class "Bit Need. The S800'. Feil out of cement at 6570'. Tested splice to 10002. This of 5700'. Circulated up thick mud. Tit to 8800'. Fuel to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. <	WELL XX WELL	OTHER	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 9. Non dame of wideal Acargy State of South Fourth Street - Artesia, NM 88210 4. Well Location Usit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 10. Elevation (Skow whether DF, RKB, RT, GR, etc.) 4. Usit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 10. Elevation (Skow whether DF, RKB, RT, GR, etc.) 4. Usit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 10. Elevation (Skow whether DF, RKB, RT, GR, etc.) 4. Usit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 10. Elevation (Skow whether DF, RKB, RT, GR, etc.) 4. 196' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING FEST AND CEMENT JOB DOTHER. PULL OR ALTER CASING OTHER: Re-entry & completion 12. Describe Proposed or Completed Operations (Clearly state all periment data), and give periment data, including enimated date of staning any proposed weekly State ML 103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. Rest Mud Clearly state all periment data (State data) data of staning any proposed weekly data (State and State all periment data). State at 6570'. Fell ou		ORATION	2
103 South Peter Properties Interest of the south set of the southof the south set of the south set of the south s	3. Address of Operator		9. Pool name or Wildcat
Unit Letter L: 1980 Feet From The South Line and 660 Feet From The West Line Section 1 Township 145 Range 33E NMPM Lea County 10. Elevation (Show whether DF. RKB. KT. GR. etc.) 4196' DF 4196' DF Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRULING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Commence DRULING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Completion E 12 Decrube Proposed or Completed Operations (Clearly state all periversi details, and give periversi details, and give periversi details, and give periversi details, and give not to 8890'. Pust detainer. TOOH. Shut in. Wolc. 8-32-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & free and free at 6570'. Feel out of cement at 6670'. Tested splice to 10006, TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pust down for night. 1 herety certly that the informatice above in the te		eet - Artesia, NM 88210	Saunders Termo opper renn
Section 1 Township 145 Range 33E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4196' DF 10.	4. Well Location	080 - South Vieward	660 Feet From The West Line
Section 1 Towning 143 Knoge 212 Norm Instruction 10 Eventual GRow Watter DT, KR, RT, GR, etc.) 4196' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Altering Casing PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: CASING TEST AND CEMENT JOB OTHER OTHER: Re-entry & completion E 12 Describe Proposed or Completed Openations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 TH to 8800'. Rig up swively. Wash down to 8890'. Pushed something alead of bit to 8897'. Thild to 8902'. Getting iron cuttings in returns – no rubber. 1 hereby certy that the date due, Circulated clean. TOOH. TH to 800'.		Feet From The Line and _	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4196' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE OF INTENTION TO: PULG AND ABANDON COMMENCE OF INTENTION TO: COMMENCE OF INTENTION TO: PULG AND ABANDON COMMENCE ORIGINATION OF CHANGE PLANS PULG AND ABANDON PULG AND ABANDON COMMENCE ORIGING OPNS. PLUG AND ABANDONMENT COMMENCE ORIGING OPNS. PLUG AND ABANDONMENT COMMENCE ORIGING OPNS. PLUG AND ABANDONMENT COMMENCE ORIGING OPNS. PLUG AND ABANDON OTHER: COMMENCE ORIGING OPNS. PLUG AND AB	Section 1	Township 14S Range 33E	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: OTHER: Re-entry & completion 8 12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed wort) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & retainer at 6570'. Tested splice to 10006. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. I hereby certly that the information above is traceful complete to the best of my traveledge and belief. SIONATURE MATHANANA		10. Elevation (Show whether DF, RKB, RT, GR,	, etc.)
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER OTHER: COMPLet OFFICE COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT 12. Describe Proposed or Completed Operations (Clearly state all pertinent dealls, and give pertinent dates, including estimated date of staring any proposed CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & 6700'. Fell out of cement at 6670'. Tested splice to 10000#. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. I hereby certify that the information above is traceful complete to the test of my traveledge and belid. stonarture Trace Production Clerk part 8-24-94. Stonarture Traceful complete to the test of my traveledge and belid.			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: COMMENCE ORPLETON & Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed work) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & retainer at 6570'. Fell out of cement at 6670'. Tested splice to 1000#. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. Iberoby certify that by information above is inselfed complete to the best of my knowledge and belid. SIGNATURE THE Production Clerk DATE BUD ATTINE THE			blice, Report, or Other Data
PERFORM REMEDIAL WORK PLUG AND REARDON Interest of the set of my knowledge and belief. TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE OF TAIONS OTHER: OTHER. Commence of the set of my knowledge and belief. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & foro'. Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & foro'. Circulated up thick mud. TH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Tubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. Ihereby certly that the information above is true find complitite to the beat of my knowledge and belief. SUSTATUR	NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CANNE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Re-entry & completion E 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed work) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & retainer at 6570'. Fell out of cement at 6670'. Tested splice to 10000#. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. Iberoby centry that of information above is true find complete to the best of my knowledge and beird. SIGNATURE TIME Production Clerk Mark TIME Production Clerk SIGNATURE THE MARK 505-748-1471			
TEMPORARILY ABANDON CHANGE FORMS COMMERCE STREET CONSTRUCTION OF THE COMMERCE STREET OF THE CASING PULL OR ALTER CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: Re-entry & completion Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed work) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & 670'. Fell out of cement at 6670'. Tested splice to 1000#. TIH to 7500'. Circulated up thick mud. TH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. Ihereby certly that th information shows is true find complete to the best of my trowkedge and belief. SIGNATURE TIME Production Clerk DATE Bit locked up. Time for the for Clerk SIGNATURE THE Start All Complete to the best of my trowkedge and belief. SIGNATURE THE Start All Complete to the best of my trowkedge and belief. SIGNATURE Signation shows is true find complete to the best of my trowkedge and belief.			
OTHER: OTHER: Re-entry & completion I2 Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of staring any proposed work) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & retainer at 6570'. Fell out of cement at 6670'. Tested splice to 1000#. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. Ihereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE TIME Production Clerk DATE BIT HEOR PRINT NAME Klein	TEMPORARILY ABANDON		
OTHER:	PULL OR ALTER CASING		
12. Describe Proposed or Completed Operations (Clearly state all periment datals, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. CONTINUED FROM PREVIOUS PAGE: Class "H" Neat. Displaced with mud 1/2 short of retainer. Sting out of retainer. TOOH. Shut in. WOC. 8-23-94 - THH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & retainer at 6570'. Fell out of cement at 6670'. Tested splice to 1000#. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. Ihereby certify that the information above is true and complete to the best of my knowledge and belief. Stonarure		OTHER: Re-	-entry & completion
Shut in. WOC. 8-23-94 - TIH w/4-3/4" bit, 6 3-1/2" drill collars. Tag cement at 6525'. Drill cement & retainer at 6570'. Fell out of cement at 6670'. Tested splice to 1000#. TIH to 7500'. Circulated up thick mud. TIH to 8800'. Rig up swivel. Wash down to 8890'. Pushed something ahead of bit to 8897'. Drilled to 8912'. Getting iron cuttings in returns - no rubber. Bit locked up. Circulated clean. TOOH. Bit worn out. Shut in and shut down for night. I hereby certify that the information above is true find complete to the best of my knowledge and belief. SIONATURE TITLE_Production Clerk Parte_8-24-94 505-748-1471 TIME OR FRINT NAME			
SIONATURE AUSTY Klein TILE Production Clerk DATE 8-24-94 505-748-1471 TELEPHONE NO.	12. Describe Proposed or Completed C work) SEE RULE 1103. CONTINUED FROM PREVIO	DUS PAGE:	dates, including estimated date of starting any proposed
	12 Describe Proposed or Completed C work) SEE RULE 1103. CONTINUED FROM PREVIO Class "H" Neat. Disp Shut in. WOC. 8-23-94 - TIH w/4-3/4 retainer at 6570'. H Circulated up thick m thing ahead of bit to rubber. Bit locked up	DUS PAGE: Delaced with mud 1/2 short of retainer W bit, 6 3-1/2" drill collars. Tag Fell out of cement at 6670'. Tested nud. TIH to 8800'. Rig up swivel.	dates, including estimated date of starting any proposed . Sting out of retainer. TOOH. cement at 6525'. Drill cement & splice to 1000#. TIH to 7500'. Wash down to 8890'. Pushed some- iron cuttings in returns - no
	 12. Describe Proposed or Completed C work) SEE RULE 1103. CONTINUED FROM PREVIO Class "H" Neat. Disp Shut in. WOC. 8-23-94 - TIH w/4-3/4 retainer at 6570'. F Circulated up thick m thing ahead of bit to rubber. Bit locked u for night. 	DUS PAGE: Delaced with mud 1/2 short of retainer " bit, 6 3-1/2" drill collars. Tag Fell out of cement at 6670'. Tested mud. TIH to 8800'. Rig up swivel. De 8897'. Drilled to 8912'. Getting up. Circulated clean. TOOH. Bit wo e is true and complete to the best of my knowledge and belief. TIME Produ	Actes, including estimated date of starting any proposed Sting out of retainer. TOOH. cement at 6525'. Drill cement & splice to 1000#. TIH to 7500'. Wash down to 8890'. Pushed some- iron cuttings in returns - no orn out. Shut in and shut down Action Clerk