

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
64-033151

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Tenneco Federal

9. WELL NO. **1**

10. FIELD AND POOL, OR WILDCAT
Undesignated

11. SEC. T. R. M., OR BLK. AND
SURVEY OR AREA
Sec. 31, T 14S, R 35E

12. COUNTY OR PARISH **Lea** 13. STATE **N. Mex.**

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. NAME OF OPERATOR
OLEN F. FEATHERSTONE

3. ADDRESS OF OPERATOR
236 Petroleum Building, Roswell, New Mexico, 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FNL & 1980' FNL Sec. 31, T 14S, R 35E, N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4057 GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Dec. 12, 1967 Spud.

Jan. 16, 1968 Total Depth - 10,600' KB.

Jan. 17, 1968 Ran 10,552' new 5-1/2" casing as follows:

2702'	20#	N-80	Top
500'	17#	J-55	
1500'	15.5#	J-55	
1800'	17#	J-55	
3650'	20#	N-80	Bottom

Larkin guide shoe on bottom. Float collar at 10,520'. Centralizers and wall cleaners bottom 300'.

Halliburton cemented 200 sacks Pozmix "A" 1:1 ratio consisting of 100 sacks Lonestar Incor F and 100 sacks Pozmix "A" with 2% gel. 16 sacks salt and 126# CFR-2. Plug down 5:00 p.m. Pressure tested 2000# for 30 minutes with no pressure loss.

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. Hicks
(Charles W. Hicks)

TITLE

General Manager

DATE **January 13, 1968**

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 23 1968

*See Instructions on Reverse Side

**J L GORDON
ACTING DISTRICT ENGINEER**

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 1: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.