| DISTRIBUTION  |   |  |  | Form C-103<br>Supersedes Old<br>C-102 and C-103 |                       |
|---|---|--|--|---|-----------------------|
| SANTA FE  | NEW   | MEXICO OIL CONSERVAT                                       | TON COMMISSION                           | Effective 1-1                                   | -68                   |
| U.S.G.S.  |   |  | •  | 5a. Indicate Typ                                | e cf Lease            |
| LAND OFFICE   |   |  |  | State   | Fee 🕱                 |
| OPERATOR  |   |  |  | 5, State Oil & Go                               | as Lease No.          |
| SUN   | DRY NOTICES A   | ND REPORTS ON WELL   | S  |   |                       |
| SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR FLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) |   |  |  | 7. Unit Agreement Name                          |                       |
| OIL GAS WELL  2. Name of Operator   | OTHER-  | P&A  |  |   | it Name               |
| Shell Oil Company (Western Division)  |   |  |  | 8. Farm or Lease Wright                         | e Name                |
| 3. Address of Operator  |   | 70904  | · · · · · · · · · · · · · · · · · · ·    | 9. Well No.                                     |                       |
| P.O. Box 1509, Midl   | and, Texas  | 79701  |  | 10. Field and Po                                | -1 3/21 1             |
| UNIT LETTER B   | 5 <b>6</b> 0 FEET F   | FROM THE North LINE  | AND FEET FROM                            | Wildcat (P                                      | -                     |
| THE East Line, see  | 20  | TOWNSHIPR  | 37 <b>-E</b>                             |   |                       |
|   |   |  |  |   |                       |
|   | (   | evation (Show whether DF, RT, 79 <b>DF</b> 3861 <b>G</b> F | •  | 12. County                                      |                       |
| 16. Chec  |   |  | ·  | Lea   | _411111111            |
| NOTICE OF   | INTENTION TO  | Sox To Indicate Nature (                                   |  | ner Data<br>T REPORT OF:                        |                       |
| PERFORM REMEDIAL WORK   | P   | PLUG AND ABANDON REMED                                     | AL WORK                                  | Alten   | ING CASING            |
| TEMPORARILY ABANDON   |   | <del>-</del>   | NCE DRILLING OPNS.                       |   | AND ABANDONMENT       |
| PULL OR ALTER CASING  | c   | HANGE PLANS CASING   | TEST AND CEMENT JOB                      |   |                       |
| OTHER   |   | ОТН  | ER                                       |   |                       |
|   |   |  |  |   |                       |
| 17. Describe Proposed or Completed work) SEE RULE 1103.   | Operations (Clearly   | state all pertinent details, and                           | give pertinent dates, including          | estimated date of s                             | starting any proposed |
| 1. Spotted plugs to 2. Plugged W/190 so 25 Sacks - 12,5 25 Sacks - 10,9 25 Sacks - 9,94 25 Sacks - 8,66 25 Sacks - 6,20 65 Sacks - 4,87 3. Plugged & aband 4. Erected prescri                           | macks Trinity 00' TD to 12 00' to 10 0' to 9, 7' to 8, 0' to 6, 0' to 4, oned 3-17-68 | ,830°<br>870°<br>197°<br>130°<br>720°                      | ixed 15.6#/ <b>G</b> al <b>l</b> on      | as follows:                                     |                       |
| ORIGINAL SICKED BY D. L. L. D   | on above is true and  L. Lilly  |  | vledge and belief.<br>echanical Engineer | DATE March                                      | n 25, 1968            |
| APPROVED BY   | unyan   | TITLE  | 3  |   |                       |
| CONDITION OF APPROVAL, IF AN  | ıy:   |  |  |   |                       |