This form is <u>not</u> to be used for reporting packer leakage tests in Northwest New Mexico

## NEW MEXICO OIL CONSERVATION COMMISSION

÷

## SOUTHEAST NEW MEXICO PACKER LEAKAGE TEST

Operator The Superior Oil Company	Leas	e State "K"	1.1	ell
Location Unit Sec	Twp	Rge	County	0. 1
of Well J 4	14-S Type of Prod	Method of Prod	Prod. Medium	Lea Choke Siz
Name of Reservoir or Pool Upper Undesignated	(Oil or Gas)	Flow, Art Lift	(Tbg or Csg)	ONORE DIZE
Compl Lower Wolfcamp Zone	0i1	Flowing	Tbg - 2-3/8"	22/64"
Lower Cerca Compl Upper Penn.	0i1	<b>Fl</b> owing	Tbg - 2-3/8"	3/4"
Both zones shut-in at (hour, date):_	FLOW TEST Lower Wolfcamp Upper Penn. sh	shut in at 6:40	on November 5, 1	968
Well opened at (hour, date): 6:45 P	M on November 5	, 1968	Upper Completion	Lower Completic
Indicate by ( X ) the zone producing	• • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	•••••	X
Pressure at beginning of test	• • • • • • • • • • • • • • • •	•••••	<u>900 psig</u>	60 psig
Stabilized? (Yes or No)	•••••	• • • • • • • • • • • • • • • • • •	•••••• <u>Y</u> es	Yes
Maximum pressure during test	• • • • • • • • • • • • • • • • •		900 psig	65 psig
Minimum pressure during test	• • • • • • • • • • • • • • • •		890 psig	60 psig
Pressure at conclusion of test	••••••••		890 psig	60 psig
Pressure change during test (Maximum	minus Minimum).		<u>10 psig</u>	5 psig
Mas pressure change an increase or a	decrease?			decrease
Vell closed at (hour, date): 4:45 PM Dil Production	Gas Prod	uction	on 22 hrs.	
During Test: 354 bbls; Grav. 45.	4; During T	'est223	MCF: GOR 63	0
Remarks Upper Penn (Lower Compl.) wa				
	s not shut in f	or an extended pe	riod prior to fl	
Remarks Upper Penn (Lower Compl.) wa	s not shut in f	or an extended pe one to kick off f	riod prior to fl	
Remarks Upper Penn (Lower Compl.) wa	s not shut in f to swab this z FLOW TEST N	or an extended pe one to kick off f 10.2	riod prior to fl	ow test Lower
Remarks Upper Penn (Lower Compl.) wa No. 1, since it is necessary Well opened at (hour, date): <u>4:15 PM</u>	s not shut in f to swab this z FLOW TEST N on November 7,	or an extended pe one to kick off f 10. 2 1968	riod prior to f1 lowing. Upper Completion	ow test Lower Completio
Remarks_Upper Penn (Lower Compl.) wa No. 1, since it is necessary	s not shut in f to swab this z FLOW TEST N on November 7,	or an extended pe one to kick off f 10. 2 1968	riod prior to f1 lowing. Upper Completion X	ow test Lower Completio
Remarks Upper Penn (Lower Compl.) wa No. 1, since it is necessary Well opened at (hour, date): 4:15 PM Indicate by ( X ) the zone producin Pressure at beginning of test	s not shut in f to swab this z FLOW TEST N on November 7,	or an extended pe one to kick off f 10. 2 1968	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u>	ow test Lower Completio
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by ( X ) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a	s not shut in f to swab this z FLOW TEST N on November 7, ng	or an extended pe one to kick off f 10. 2 1968 hrs. after opene	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u> d. <u>Yes</u>	ow test Lower Completio <u>360 psig</u> Yes
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by ( X ) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a: Maximum pressure during test	s not shut in f to swab this z FLOW TEST N on November 7, ng.	or an extended pe one to kick off f 10. 2 1968 hrs. after opene	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u> d. <u>Yes</u> <u>465 psig</u>	ow test Lower Completio 360 psig Yes 364 psig
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): <u>4:15 PM</u> Indicate by ( X ) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a Maximum pressure during test	s not shut in f to swab this z FLOW TEST N on November 7, ng pproximately 16	or an extended pe one to kick off f 10. 2 1968 hrs. after opene	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u> d <u>Yes</u> <u>465 psig</u> <u>385 psig</u>	ow test Lower Completio 360 psig Yes 364 psig 360 psig
Remarks Upper Penn (Lower Compl.) wa No. 1, since it is necessary Well opened at (hour, date): 4:15 PM Indicate by ( X ) the zone producin	s not shut in f to swab this z FLOW TEST N on November 7, pg	or an extended pe one to kick off f 10. 2 1968 hrs. after opene	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u> d <u>Yes</u> <u>465 psig</u> <u>385 psig</u> <u>385 psig</u>	ow test Lower Completio 360 psig Yes 364 psig 360 psig 360 psig
Remarks Upper Penn (Lower Compl.) wa No. 1, since it is necessary Well opened at (hour, date): 4:15 PM Indicate by ( X ) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a Maximum pressure during test Finimum pressure during test Pressure at conclusion of test	s not shut in f to swab this z FLOW TEST N on November 7, ng	or an extended pe one to kick off f 10. 2 1968 hrs. after opene	riod prior to f1 lowing. Upper Completion X 300 psig d465 psig 465 psig 385 psig 385 psig 385 psig 80 psig 80 psig	Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 360 psig 4 psig
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): <u>4:15 PM</u> Indicate by ( X ) the zone producing Pressure at beginning of test Stabilized? (Yes or No). <u>Stabilized a</u> Maximum pressure during test Pressure at conclusion of test Pressure at conclusion of test Pressure change during test (Maximum as pressure change an increase or a ell closed at (hour, date) <u>4:00 PM of</u> il Production	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ	or an extended pe one to kick off f 10. 2 1968 hrs. after opene Total time 1968 Production	riod prior to f1 lowing. Upper Completion X 300 psig d465 psig 465 psig 385 psig 385 psig 385 psig 80 psig decrease on 23 hrs & 45	ow test Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 4 psig decrease min.
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by (X) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a Maximum pressure during test Fressure at conclusion of test Pressure at conclusion of test Pressure at conclusion of test Pressure change during test (Maximum as pressure change an increase or a ell closed at (hour, date) 4:00 PM il Production Puring Test: 472 bbls; Grav. 43.4	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ 6 ;During Te	or an extended pe one to kick off f 10. 2 1968 hrs. after opene hrs. after opene Total time 1968 Production ction st 577	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u> d. Yes <u>465 psig</u> <u>385 psig</u> <u>385 psig</u> <u>385 psig</u> <u>385 psig</u> <u>80 psig</u> <u>decrease</u> on 23 hrs & 45	Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 360 psig 4 psig decrease min.
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by (X) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized an faximum pressure during test Fressure at conclusion of test Pressure at conclusion of test Pressure change during test (Maximum as pressure change an increase or a fell closed at (hour, date) 4:00 PM of 11 Production uring Test: 472 bbls; Grav. 43.0 emarks Following packer leakage test Penn. (lower completion) was	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ 6;During Te t, Lower Wolfcar opened up on 3,	or an extended pe one to kick off f 10. 2 1968 hrs. after opene hrs. after opene Total time 1968 Production ction st 577 np (upper complet /4" ch. but faile	riod prior to f1 lowing. Upper Completion X 300 psig d. Yes 465 psig 465 psig 385 psig 385 psig 385 psig 385 psig 80 psig decrease on 23 hrs & 45 p MCF; GOR 1222 ion) wasshut in	Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 360 psig 4 psig decrease min.
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by (X) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized at Maximum pressure during test Fressure at conclusion of test Pressure at conclusion of test Pressure change during test (Maximum as pressure change an increase or a ell closed at (hour, date) 4:00 PM il Production uring Test: 472 bbls; Grav. 43.0 emarks Following packer leakage test Penn. (lower completion) was was swabbed in flowing at 11 hereby certify that the information	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ 6;During Te t, Lower Wolfcan opened up on 3, :30 AM on Noveml	or an extended pe one to kick off f 10. 2 1968 hrs. after opene hrs. after opene Total time 1968 Production ction st 577 np (upper complet /4" ch. but failed ber 10, 1968.	riod prior to f1 lowing. Upper Completion X 300 psig d465 psig 465 psig 465 psig 385 psig 385 psig 385 psig 385 psig 	ow test Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 4 psig decrease min. and Upper r Penn. Zond
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by (X) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a faximum pressure during test finimum pressure during test Pressure at conclusion of test Pressure change during test (Maximum as pressure change an increase or a cell closed at (hour, date) 4:00 PM of Production Puring Test: 472 bbls; Grav. 43.4 emarks Following packer leakage test Penn. (lower completion) was was swabbed in flowing at 11 hereby certify that the information nowledge.	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ 6 ;During Ten t, Lover Wolfcan opened up on 3, :30 AM on Novem herein contain	or an extended pe one to kick off f 10. 2 1968 hrs. after opene hrs. after opene Total time 1968 Production ction st 577 np (upper complet /4" ch. but failed ber 10, 1968. ed is true and com	riod prior to f1 lowing. Upper Completion <u>X</u> <u>300 psig</u> d. Yes <u>465 psig</u> <u>385 psig</u> <u>385 psig</u> <u>385 psig</u> <u>385 psig</u> <u>385 psig</u> <u>80 psig</u> <u>decrease</u> on 23 hrs & 45 MCF; GOR <u>1222</u> ion) wasshut in d to flow. Uppe	Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 360 psig 4 psig decrease min. and Upper r Penn. Zono st of my
Remarks Upper Penn (Lower Compl.) wa No. 1, since it is necessary Well opened at (hour, date): 4:15 PM Indicate by (X) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a faximum pressure during test Fressure at conclusion of test Pressure at conclusion of test Pressure change during test (Maximum Tas pressure change an increase or a cell closed at (hour, date) 4:00 PM fil Production Puring Test: 472 bbls; Grav. 43.4 emarks Following packer leakage test Penn. (lower completion) was was swabbed in flowing at 11 hereby certify that the information nowledge.	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ 6;During Test t, Lower Wolfcan opened up on 3, :30 AM on Novem herein contained	or an extended pe one to kick off f 10. 2 1968 hrs. after opene hrs. after opene Total time 1968 Production ction st 577 np (upper complet /4" ch. but failed ber 10, 1968.	riod prior to f1 lowing. Upper Completion X 300 psig d465 psig 465 psig 465 psig 385 psig 385 psig 385 psig 385 psig 	ow test Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 4 psig decrease min. and Upper r Penn. Zond st of my
No. 1, since it is necessary No. 1, since it is necessary Nell opened at (hour, date): 4:15 PM Indicate by (X) the zone producin Pressure at beginning of test Stabilized? (Yes or No). Stabilized a faximum pressure during test finimum pressure during test Pressure at conclusion of test Pressure change during test (Maximum as pressure change an increase or a fell closed at (hour, date) 4:00 PM fil Production uring Test: 472 bbls; Grav. 43.4 emarks Following packer leakage test Penn. (lower completion) was was swabbed in flowing at 11 hereby certify that the information nowledge.	s not shut in f to swab this z FLOW TEST N on November 7, og pproximately 16 minus Minimum). decrease? on November 8, Gas Produ 6;During Test t, Lower Wolfcan opened up on 3, :30 AM on Novem herein contained pon y	or an extended pe one to kick off f 10. 2 1968 hrs. after opene frotal time 1968 Production ction st 577 np (upper complet 74" ch. but failed ber 10, 1968. ed is true and complet 75. D. 6	riod prior to f1 lowing. Upper Completion X 300 psig d465 psig 465 psig 465 psig 385 psig 385 psig 385 psig 385 psig 	Lower Completio 360 psig Yes 364 psig 360 psig 360 psig 360 psig 4 psig decrease min. and Upper r Penn. Zond st of my



т.) 1 п