

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-22765
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K-6272 B-399-35

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name State 19
2. Name of Operator Petroleum Production Management, Inc.	8. Well No. 1
3. Address of Operator Suite 200/Sutton Place Bldg. Wichita, Kansas 67202	9. Pool name or Wildcat Baum Upper Penn and North Baum Wolfcamp
4. Well Location Unit Letter I : 660 Feet From The East Line and 1980 Feet From The South Line Section 19 Township 13-S Range 33-E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4279' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Commingle down hole ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-24-91—Rig up unit. Pulled out of hole with rods and tubing.
8-26-91—Tripped in hole with retrieving tool and latched on to retrievable bridge plug. No success moving bridge plug. Pulled out of hole. Tripped in hole with over-shot, bumper sub, jars and 6 drill collars. Worked RBP loose.
8-27-91—Pulled out of hole. Laid down tools and RBP. Tripped in hole with tubing and set down at 9500'. Pulled out of hole.
8-28-91—Tripped in hole with bit and bailer. Set down at 9500'. Could not make hole. Pulled out of hole. Tripped in hole with 3 3/4" swage. Worked through tight casing.
8-29-91—Pulled out of hole. Tripped in hole with 4 5/8" swage. Worked through tight casing.
8-30-91—Pulled out of hole with swage. Laid down all tools. Tripped in hole with 2 3/8" tubing. Set at 9698'. Ran pump and rods. Hung well on beam.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gary T. Cothran TITLE District Superintendent DATE 9-4-91

TYPE OR PRINT NAME Gary T. Cothran TELEPHONE NO. 675-2478

(This space for State Use)

ORIGINAL SIGNED BY JIMMY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 20 1991