	NEW MEXICO	n and a second and a
ENERGY AND MINE	CONSERVATION DIVISION	
DISTRIBU	P O. BOX 2088	Form C-103 Revised 19-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501	
FILE U.S.Q.S.		Sa. Indicate Type of Leose State A Fee
LAND OFFIC		5. State Oil 6 Gas Lease No.
OPERATOR		B-399-35
(00 NOT USE	SUNDRY NOTICES AND REPORTS ON WELLS	
eit. 8		7. Unit Agreement Name
Name of Operator		8. Farm of Lease liame
The Mauri	Lce L. Brown Co.	State 19
Address of Operat	)/ Sutton Place Bldg./ Wichita, Kansas 67202	9. Well No.
Location of Well	J Ducton Trace Drug., aroni on a same a	10, Field and Pool, or Wildcat
	I 1980' FEET FROM THE South LINE AND 660'	Upper Penn
UNIT LETTER		and the second of the second
THE East	LINE, SECTION 19 TOWNSHIP 135 RANGE 33E	Child & MANTITTTTTTTTTT
mmm	TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	12. County
AHHHHH	4279'KB, 4278'DF, 4267'GL	Lea
16.	Check Appropriate Box To Indicate Nature of Notice, Report	or Other Data
		QUENT REPORT OF:
PERFORM REMEDIAL	WORK PLUG AND ABANDON PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABAND		PLUG AND ABANDONMENT
PULL OR ALTER CARE	NG CHANGE PLANS CASING TEST AND CEMENT JQB	
	отнея	
OTHER		
17. Describe Propor work) SEE RUL	sod or Completed Operations (Clearly state all pertinent details, and give pertinent dates, 1 E 1103.	ncluding estimated date of starting any proposed
3-02-79	Moved in and rigged up PBCP Services, Inc. P	ulled out of hole with
	tabing	
3-05-79	Went in hole with $5\frac{1}{2}$ " casing scraper. Tagged out of hole with scraper. Started in hole wi	th Betrievable Bridge
	Dime and Dang Dookon	
2.06-79	Completed going in hole with Retrievable Brid	ge Plug and RTTS Packer.
3-00-79	Set Retrievable Bridge Plug at 9581'KB. Set	RTTS at 9490'KB.
	Chambad ano hhing	
3-07-79	through 3-15-79 Swab tested Bough "C" perfor	actons (7/327/4/.).
~ */ =~	Final water cut 35 to 50 per cent. Ran Dresser-Atlas Temperature Base Log. Log	showed fluid flow from
3-16-79		
3-17-79	Raised and set bridge plug at 9718'. Left RT	TS swinging above
-	Bridge Plug.	
3-19-79	- Such tested nertorations from 95501-97001.	nd nacker. Left Re-
3-20-79	to 3-23-79 Pulled out of hole with tubing ar trievable Bridge Plug in hole at 9718' depth.	Installed pumping
	equipment and rigged down PBCP Services, Inc	· · · · · · · · · · · · · · · · · · ·
18. I hereby certify	that the information above is true and complete to the best of my knowledge and belief.	
NICHED UM	Moesbeck District Engineer	DATE 3-29-79
	Orig. Signed by	APR 9 1979
	Jerry Sexton Dist 1, Supv.	APR 9 1979
	PROVAL, IF ANY:	

## RECEIVED APR 6 1979 OIL CONSERVATION COMM. BOODS, N. M.

1

- Maria