

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Olen F. Featherstone		8. Term or Lease Name Elkan
3. Address of Operator 1717 West Second Street, Roswell, NM 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>14 S.</u> RANGE <u>34 E.</u> N.M.P.M.		10. Field and Pool, or Willcut WILDCAT
15. Elevation (Show whether DF, RT, GR, etc.) 4101' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-26-68 Spud.

2-7-69 TD - 10,745'.

Feb., 1969 P.B. and temporarily abandoned - See Sundry Notice dated 2-10-69

\* \* \* \* \*

Cement plug in bottom 8 5/8" casing set at 4500' (Gr. measurements).  
Intend to complete plugging and abandon as follows:

- 1) Pull 8 5/8" casing.
- 2) 65 sack cement plug - one half in and one half out of 8 5/8" stub.
- 3) 80 sack cement plug - 100' in bottom 12 3/4" casing at 410'.
- 4) 10 sack cement plug at surface and set 4 1/2" marker pipe 4' above surface.
- 5) Will use 9.5# mud between cement plugs.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

OLEN F. FEATHERSTONE

SIGNED Charles W. Hicks  
Charles W. Hicks

TITLE General Manager

DATE Sept. 25, 1973

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: