NO. OF COPIES RECE	IVED				
DISTRIBUTIO	DISTRIBUTION				
SANTA FE					
FILE	FILE				
U.S.G.S.	U.S.G.S.				
LAND OFFICE	LAND OFFICE				
TRANSPORTER	<u> </u>				
TRANSFORTER					
OPERATOR					
PRORATION OF		<u> </u>			

NEW MEXICO OIL CONSERVATION COMMISSION REQUEST FOR ALLOWABLE AND

Form C -104 Supersedes Old C-104 and C-110 Effective 1-1-65

			_1	ALITH	ORIZAT	ION TO TR	ANSPUR I (IL AND N	LIUKAL	GAS		
.s.g.s.				AUIN	· · · · · ·				- 4			
AND OFFICE							• •	t gat language a	1.1			
BANCPORTER	OIL											
RANSPORTER	GAS											
PERATOR							•					
PRORATION OF	FICE											
perator												
MJ :	Produc	ing	Comp	any								-
ddress												
4:	13 Fir	at 1	Vatio	mal Ran	nk Bld	g., Midla						
leason(s) for filing	(Check	proper	box)					ther (Please				
lew Well				Change	in Transp	orter of:	_	Change	of Leas	se name i	from Bar	m B Stat
Recompletion	\Box			Oil	[Dry (Gas	_				
Change in Owners				Casingh	nead Gas	Cond	ensate	to bat	m b bc	ate Com		
change of owne nd address of pr	ership giv evious ov	ve nar wner	ne									
ESCRIPTION	OF WEI	LL A	ND LI	EASE					Kind of Le	ase .		Legse No
_ease Name				Well No		ame, Including			State, Fede		State	K-3846
Baum B	State	Co	m	1	Ba	um Upper	Penn		Siute, rede		<u> </u>	K-6444
_ocation								_				K~0444
_	L		19	30 Feet F	From The	South,	_ine and6	60	_ Feet Fro	m The We	9E	
Unit Letter		_ ;			.0					_		_
Line of Section	4		Town	shin	14 S	Range	33E	, NMPM,		<u>Le</u>	8	Count
ESIGNATION Name of Authoriz	of TRA	ANSI orter	of Oil	ER OF O	IL AND	NATURAL C		Give address t			this form is	to be sent)
DESIGNATION Name of Authoriz Admiral Name of Authoriz	rude (ed Transp	orter o	Corport Casin	oration	r Condense	NATURAL (Box Address (713, Md Give address	land, To which app	exas proved copy of	this form is	
Name of Authoriz	rude (ed Transp	orter o	Corport Casin	oration	r Condense	Dry Gas	Box Address (713, Md Give address to 1589, Tu	land, To which apples of the control	exas proved copy of Lahoms		
Name of Authoriz Admiral (Name of Authoriz Warren Pe	ed Transper (Project Colet	orter of	Corp of Casi	oration nghead Gas ration Unit	Sec.	Dry Gas	Address (Eox Is gas act	713, Mid Give address to 1589, Tu	land, To which apples of the control	exas proved copy of	this form is	
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of t	ed Transport of Tr	orter o	Corport Casin	oration nghead Gas ration Unit	Sec.	Dry Gas	Address (Eox Is gas act	713, Mid Give address to 1589, Tu qually connected no	land, To which apple 188, Ok	exas proved copy of Lahoms	this form is	
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of t	ed Transport of Tr	orter o	Corport Casin	oration nghead Gas ration Unit	Sec.	Dry Gas	Address (Eox Is gas act	713, Mid Give address to 1589, Tu qually connected no	land, To which apple 188, Ok	exas proved copy of Lahoms	this form is	
Name of Authoriz Admiral C Name of Authoriz Warren Pe If well produces give location of t If this production	ed Transpectrolet oil or liquianks. n is comm	orter o	Corport Casin	oration nghead Gas ration Unit	Sec.	Dry Gas Twp. Rge. 14 3.	Address (Box Is gas act ol, give comm	713, Md Give address a 1589, Tu wally connected no ningling order	land, I o which ap lase, Ok ed?	exas proved copy of Latroma When	this form is 74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of the production of the product	ed Transpectude (ed Transpectude) et rolet coil or liquidanks. n is comm	orter orter ids,	Corpor Cash	oration nghead Gas ration Unit S	Sec.	Dry Gas Twp. Rge. 14 3.	Address (Box Is gas act ol, give comm	713, Mid Give address to 1589, Tu qually connected no	land, To which apple 188, Ok	exas proved copy of Latroma When	this form is 74102	s to be sent)
Name of Authoriz Admiral C Name of Authoriz Warren Pe If well produces give location of t If this production	ed Transpectude (ed Transpectude) et rolet coil or liquidanks. n is comm	orter orter ids,	Corpor Cash	oration nghead Gas ration Unit S	Sec.	Dry Gas Twp. Rge. 14 3.	Address (Eox Is gas act New Well	713, Mdd Give address (1589, Tu ually connecte no ningling orde	land, I o which ap lase, Ok ed?	Plug Bac	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate '	ed Transpectude (ed Transpectude) et rolet coil or liquidanks. n is comm	orter orter ids,	Corpor Cash	oration nghead Gas ration Unit S	Sec. 4	Dry Gas Twp. Rge. 14 3. er lease or pool	Address (Box Is gas act ol, give comm	713, Mdd Give address (1589, Tu ually connecte no ningling orde	land, I o which ap lase, Ok ed?	exas proved copy of Latroma When	74102	
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of the production of the product	ed Transpectude (ed Transpectude) et rolet coil or liquidanks. n is comm	orter orter ids,	Corpor Cash	oration Inghed Gas ration Unit I I had from	Sec. 4	Dry Gas Twp. Rge. 14 3. er lease or pool	Address (Eox Is gas act ol, give comm New Well Total De	713, Mid Give address a 1589, Tu mally connected ingling order	land, I o which ap lase, Ok ed?	P.B.T.D	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded	ed Transperied (ed Transperied oil or liquidanks. In is communicated of the communicated oil or liquidanks. Type of	orter	Corport Cash	oration Inghed Gas ration Unit I I had from	Sec. or any other	Dry Gas Rec. 14 3. Gas Well co Prod.	Address (Eox Is gas act New Well	713, Mid Give address a 1589, Tu mally connected ingling order	land, I o which ap lase, Ok ed?	Plug Bac	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of t f this production COMPLETION Designate (Date Spudded	ed Transperied (ed Transperied oil or liquidanks. In is communicated of the communicated oil or liquidanks. Type of	orter	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. or any other	Dry Gas Rec. 14 3. Gas Well co Prod.	Address (Eox Is gas act ol, give comm New Well Total De	713, Mid Give address a 1589, Tu mally connected ingling order	land, I o which ap lase, Ok ed?	Plug Bod	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transperied (ed Transperied oil or liquidanks. In is communicated of the communicated oil or liquidanks. Type of	orter	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. or any other	Dry Gas Rec. 14 3. Gas Well co Prod.	Address (Eox Is gas act ol, give comm New Well Total De	713, Mid Give address a 1589, Tu mally connected ingling order	land, I o which ap lase, Ok ed?	Plug Bod	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of t f this production COMPLETION Designate '	ed Transperied (ed Transperied oil or liquidanks. In is common part of the common part o	orter	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 1	Dry Gas Twp. Rge. 14 3. er lease or pool Gas Well to Prod.	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu qually connecte no hingling orde: Workover	land, 1 o which applies, Ok ad? number:	Plug Bod	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transperied (ed Transperied oil or liquidanks. In is common part of the common part o	orter	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 1	Dry Gas Twp. Rge. 14 3. er lease or pool Gas Well to Prod.	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu qually connecte no hingling orde: Workover	land, 1 o which applies, Ok ad? number:	Plug Bod	this form is 74102 Same F	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transpirude (ed Transpirude) et Tolet oil or liquidanks. In is comm DATA Type of	M1 orter of M1	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 6 any other oil Well oil. Ready t	Dry Gas Twp. Rge. 14 3. Per lease or pool Gas Well To Prod. Formation	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu qually connecte no hingling orde: Workover	land, I o which applies, Ok od?	Plug Bod	74102	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transperied (ed Transperied oil or liquidanks. In is common part of the common part o	M1 orter of M1	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 6 any other oil Well oil. Ready t	Dry Gas Twp. Rge. 14 3. er lease or pool Gas Well to Prod.	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu rually connecte no hingling order Workover	land, I o which applies, Ok od?	Plug Bod	this form is 74102 Same F	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of t f this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transpirude (ed Transpirude) et Tolet oil or liquidanks. In is comm DATA Type of	M1 orter of M1	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 6 any other oil Well oil. Ready t	Dry Gas Twp. Rge. 14 3. Per lease or pool Gas Well To Prod. Formation	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu rually connecte no hingling order Workover	land, I o which applies, Ok od?	Plug Bod	this form is 74102 Same F	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transpirude (ed Transpirude) et Tolet oil or liquidanks. In is comm DATA Type of	M1 orter of M1	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 6 any other oil Well oil. Ready t	Dry Gas Twp. Rge. 14 3. Per lease or pool Gas Well To Prod. Formation	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu rually connecte no hingling order Workover	land, I o which applies, Ok od?	Plug Bod	this form is 74102 Same F	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of t f this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transpirude (ed Transpirude) et Tolet oil or liquidanks. In is comm DATA Type of	M1 orter of M1	Corport Cash	oration nghead Gas ration Unit that from $1 - (X)$ Date Comp	Sec. 6 any other oil Well oil. Ready t	Dry Gas Twp. Rge. 14 3. Per lease or pool Gas Well To Prod. Formation	Address (Box Is gas act Is gas act New Well Total Dep	713, Mdd Give address (1589, Tu rually connecte no hingling order Workover	land, I o which applies, Ok od?	Plug Bod	this form is 74102 Same F	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of t f this production COMPLETION Designate (Date Spudded Elevations (DF, Perforations	ed Transpirude (ed Transpirude) (ed Tran	ONLI orter of the Company of the Com	Corport Cash	oration nghead Gas ration Unit S that from n - (X) Date Comp	Sec. 4 Oil Well Oi	Dry Gas Twp. Rge. 14 3. Pre lease or pool Gas Well To Prod. Formation IG, CASING, UBING SIZE	Address (Box Address (Box Is gas act New Well Total Del Top Oil/ AND CEMEN	713, Mdd Give address (1589, Tu really connecte No ringling order Workover coth Gas Pay	land, I o which applies, Ok od?	Plug Back P.B.T.D	this form is 74102 Ck Same F	to be sent) Res'v. Diff. Re
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of t f this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transpirude (ed Transpirude) (ed Tran	ONLI orter of the Company of the Com	Corport Cash	oration nghead Gas ration Unit S that from n - (X) Date Comp	Sec. 4 Oil Well Oi	Dry Gas Twp. Rge. 14 3. Presented as Well as Prod. Formation IG, CASING, UBING SIZE	Address (Box Address (Box Is gas act New Well Total Del Top Oil/ AND CEMEN	713, Mdd Give address (1589, Tu qually connected no hingling order Workover TING RECOI DEPTH S	land, I o which applies of the control of load	Plug Back P.B.T.D	this form is 74102 Ck Same F	to be sent) Res'v. Diff. Re
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF, Perforations HO TEST DATA OIL WELL	ed Transpirude (ed Transpirude) ed Transpirude oil or liquidanks. In is committed DATA Type of RKB, RT,	orter of M1 orter	Corport Cash	oration Indeed Gas ration Unit S Inthat from In - (X) Date Comp Name of Pi CAS	Sec. 4 A any other of the second of the seco	Dry Gas Twp. Rge. 14 3. Presented as Well as Prod. Formation IG, CASING, UBING SIZE	Address (Box Is gas act Is gas act New Well Total Del Top Oil/ AND CEMEN	713, Mid Give address (1589, Tu really connected Workover Workover TING RECOI DEPTH S Try of total vol for full 24 how	land, I o which applies, Ok od? I number: Deepen Deepen	Plug Back P.B.T.D Tubing I	this form is 74102 Ck Same F	to be sent) Res'v. Diff. Re
Name of Authoriz Admiral (Name of Authoriz Warrem Pe If well produces give location of t f this production COMPLETION Designate (Date Spudded Elevations (DF,	ed Transpirude (ed Transpirude) ed Transpirude oil or liquidanks. In is committed DATA Type of RKB, RT,	orter of M1 orter	Corport Cash	oration nghead Gas ration Unit S that from n - (X) Date Comp	Sec. 4 A any other of the second of the seco	Dry Gas Twp. Rge. 14 3. Presented as Well as Prod. Formation IG, CASING, UBING SIZE	Address (Box Is gas act Is gas act New Well Total Del Top Oil/ AND CEMEN	713, Mdd Give address (1589, Tu qually connected no hingling order Workover TING RECOI DEPTH S	land, I o which applies, Ok od? I number: Deepen Deepen	Plug Back P.B.T.D Tubing I	this form is 74102 Ck Same F	to be sent) Res'v. Diff. Re
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF, Perforations HO TEST DATA OIL WELL	ed Transpirude (ed Transpirude) ed Transpirude oil or liquidanks. In is committed DATA Type of RKB, RT,	orter of M1 orter	Corport Cash	oration Indeed Gas ration Unit S Inthat from In - (X) Date Comp Name of Pi CAS	Sec. 4 A any other of the second of the seco	Dry Gas Twp. Rge. 14 3. Presented as Well as Prod. Formation IG, CASING, UBING SIZE	Address (Box Address (Box Is gas act New Well Total Del Top Oil/ AND CEMEN be after recove is depth or be a	713, Md Give address to 1589, Turnally connected the mingling order workover with the state of t	land, I o which applies, Ok od? I number: Deepen Deepen	Plug Back P.B.T.D Tubing I Depth C	this form is 74102 ck Same F . Depth asing Shoe SACKS C	to be sent) Res'v. Diff. Re
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF, Perforations HO TEST DATA OIL WELL Date First New	ed Transpirude (ed Transpirude) ed Transpirude oil or liquidanks. In is committed DATA Type of RKB, RT,	orter of M1 orter	Corport Cash	oration Indeed Gas ration Unit S Inthat from In - (X) Date Comp Name of Pi CAS	Sec. 4 any other of the sec of	Dry Gas Twp. Rge. 14 3. Presented as Well as Prod. Formation IG, CASING, UBING SIZE	Address (Box Address (Box Is gas act New Well Total Del Top Oil/ AND CEMEN be after recove is depth or be a	713, Mid Give address (1589, Tu really connected Workover Workover TING RECOI DEPTH S Try of total vol for full 24 how	land, I o which applies, Ok od? I number: Deepen Deepen	Plug Back P.B.T.D Tubing I	this form is 74102 ck Same F . Depth asing Shoe SACKS C	s to be sent)
Name of Authoriz Admiral (Name of Authoriz Warren Pe If well produces give location of this production COMPLETION Designate (Date Spudded Elevations (DF, Perforations HO TEST DATA OIL WELL	ed Transpirude (ed Transpirude) ed Transpirude oil or liquidanks. In is committed to the committed of the co	orter of M1 orter	Corport Cash	oration nghead Gas ration Unit S that from - (X) Date Comp CAS Date of T	Sec. 4 any other of the sec of	Dry Gas Twp. Rge. 14 3. Presented as Well as Prod. Formation IG, CASING, UBING SIZE	Address (Box Address (Box Is gas act New Well Total Del Top Oil/ AND CEMEN be after recove is depth or be a	713, Mid Give address (1589, Tu qually connected No mingling order Workover The Gas Pay TING RECOI DEPTH S Gry of total vol for full 24 houring Method (Flo	land, I o which applies, Ok. Isa, Ok. In number: Deepen Deepen In number: Deepen In number:	Plug Back P.B.T.D Tubing I Depth C	this form is 74102 ck Same F	to be sent) Res'v. Diff. Re

GAS WELL Actual Prod. Test-MCF/D	Length of Test	Bbls. Condensate/MMCF	Gravity of Condensate
Testing Method (pitot, back pr.)	Tubing Pressure (Shut-in)	Casing Pressure (Shut-in)	Choke Size
			TION COMMISSION

VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

45010 1-	-			
6	We Co	Ph		
$\frac{\mathcal{L}}{R_{\bullet}}$	en Williams	(Signature)		
77.0 6	Vice Preside		_	
	VII.00	(Title)		
	4-23-69			
		(Date)		

	CONSERVATION	ÇQMMISSION
•	00005	1964

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II. III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.

